Appendix D: Survey Forms

This Page Intentionally Left Blank

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-1

1. Identification

County Williamson City Round Rock

Current name Various law offices Historic name N/A

Address 108 East Bagdad Avenue

Owner/address MARGARET E. JOSEPH, 3811 AZUR LN ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial building; stone veneer with standing-seam metal roof. Four office spaces with single door + window on front facade. Two doors clustered under each of two gabled dormers with windows flanking. Shallow corr. metal awning over doors.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Handicapped access south side; sidewalk slopes to parking lot.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☒ Dormers:
- ☒ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☒ Metal standing seam galv.
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☒ With transom
☒ With sidelights
☒ Other segmtl. arched transom

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 4080

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 2008 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Site of Young's Hotel (late 1800s)

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK (BLK 9 LTS 4-7 REPLAT), BLOCK 9, Lot 4A

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-2

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 304 East Bagdad Avenue

Owner/address ARMANDO & SABINA AGUILAR, 217 GREEN PASTURE DR, HUTTO,TX 78634-4004

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Ranch for sale as commercial property.Two car att. garage may have been added later. Garage converted to living space. Roof extends over porch w/ wooden posts/rails. T111-type siding on most of facade w/ 4 courses of brick immediately above slab.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other About 6 onsite parking spaces in front yard to right of front porch

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☒ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type T-111 or similar
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

1 Specify number(s)
☒ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1497

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1960 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: Garage has been converted to living space, date unknown

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 11, LOT 4 (W18'), 5-6 & 7 (E18'), (LESS N 20' OF)

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ■ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-3

1. Identification

County Williamson City Round Rock

Current name AT&T Historic name Round Rock Leader

Address 105 West Bagdad Street

Owner/address SOUTHWESTERN BELL TELEPHONE LP, ONE SBC CENTER, ROOM 36-M-01, ST LOUIS, MO 63101-3002

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Large stone block building with blanked windows on second floor; ashlar fieldstone (possibly veneer) on first floor. Main entrance through arched columns on NW corner. Stair to second floor entrance south side. Exterior rain gutters from roof on west elevation.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Large parking lot on site with approx. 15 spaces

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

6 Number of bays
☐ Stucco
☒ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☒ Other stone 2nd, veneer 1st

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other alum window wall entry

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 20,752

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☒ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☒ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1960 ☐ Actual ☒ Estimated Source: WCAD

☒ Additions/modifications, specify dates: 2nd floor modified 2001

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☒ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 1, LOT 3-10 W 1/2 OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-4

1. Identification

County Williamson City Round Rock

Current name Axis Design Historic name _____

Address 106 West Bagdad Street

Owner/address MCMLXIX LLC, 2942 CEDAR CREST CIR, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Contemporary stucco building, assymetrical design. Chimney is still extant on west side. Boxy shapes extend to new vestibule/entrance on south side. Windows are tall, with two small square lites over two tall rectangular lites. Metal awnings over all windows.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other On site parking lot with 7 spaces

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

1 Specify number(s)
☐ Interior
☒ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☒ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other square over rect lites

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☒ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other standing seam galv roof

Stories: 1+ partial 2nd **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2776

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1920 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: 2040 sq ft addition, 1923; Spanish Eclectic features removed ca. 2005

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): City of Round Rock, BLOCK 8, Lot 5pt - 6-10

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: This property was previously eligible under Criterion C for architecture; however, with the removal of those character-defining features, it is no longer eligible for the National Register.

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ■ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-5

1. Identification

County Williamson City Round Rock

Current name Round Rock Fire Station #1 Historic name

Address 200 West Bagdad Street

Owner/address CITY OF ROUND ROCK, 221 E MAIN ST ROUND ROCK,TX 78665

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Two-story fieldstone veneer plus two attached oversized garage bays for fire equipment. Arched double entry with galv metal awning, next to bay doors; 3 windows up, 1 down. Rest of front facade projects fwd with 3 windows up, 2 down.Addl entries west side.

Outbuildings (Specify number and type):

Garage 2 att. Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Flagpole south elevation next to building with landscaping

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3+3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☒ Awning(s)
☒ Other stand seam galv awning

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☐ With sidelights
☒ Other segmtl arch transom

Plan:

☒ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☒ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☒ Other Fire station

5. Architectural History

Architect: _____ Builder: _____

Construction date: 2007 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: A house was previously located where garage bays are.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): ROUND ROCK (LTS 1-5 BLK 7 REPLAT), BLOCK 7, Lot 1A, ACRES 0.415

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-6

1. Identification

County Williamson City Round Rock

Current name Upward Bound Montessori School Historic name _____

Address 201 West Bagdad Street

Owner/address MARGARET RAY FINK, 5206 RAMBLING RANGE, AUSTIN,TX 78727

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Mid-century modern with Craftsman details. Prominent front able with inset porch, concrete deck. Addition to east side since 1992, also three-car garage to rear. All with newer standing-seam metal roof. Back yard is currently a playground for students.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other backyard playground with equipment

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☒ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☒ Metal standing seam (galv.)
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type vinyl
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☒ Other casement rear addition

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☒ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☒ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☒ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other concrete deck

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1219

3. Integrity

☐ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ■ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: Addition to east and three-car attached garage after 1992.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 2, LOT 19 & 20

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-7

1. Identification

County Williamson City Round Rock

Current name Therapy Central of Round Rock (massage therapists) Historic name

Address 207 West Bagdad Street

Owner/address KENNETH R. MOENCH, 207 W BAGDAD AVE ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Cross-gabled Queen Anne cottage with jigsawn corner brackets over bay. Two rear additions.

Front porch has been altered and partially closed in; front windows have been replaced with display-type fixed single panes.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other Shed, covered in vertical wood siding, appears on 1909 Sanborn map

☐ Archeological evidence of outbuildings, specify

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☒ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal
- ☐ Other

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other

Windows:
- ☒ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other vinyl on rear addition

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☒ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other

Foundation:
- ☐ Slab ☒ Pier and beam
- ☒ Perimeter wall
- ☐ Other

Porches:
- ☒ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☒ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1463

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1905 ☐ Actual ■ Estimated Source: Sanborn maps (appears first on 1909 map)

■ Additions/modifications, specify dates: Enclosed porch, 1982

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 2, LOT 16-18

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain Although front of building has been altered, this property is otherwise intact and additionally helps to protect 208 South Blair.

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-8

1. Identification

County Williamson City Round Rock

Current name Various offices (see below) Historic name

Address 208 West Bagdad Street Office of Clifton Myers, Financial Advisor -- Party Palace -- Bluebonnet Diagnostic Imaging

Owner/address ELLEN M. STEVENS, 1005 BLUE BIRD CT ROUND ROCK,TX 78681-2743

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Gable-front-and-wing house with additional front gable section added later to create U shaped front porch.

Now divided into small offices, total of four entrances. Shed roof over front porch. Gabled side entry to west with shed-roofed porch. Large back deck.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

2 Specify number(s)
☒ Interior
☐ Exterior
☒ Brick
☐ Stone
☒ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☒ With transom
☒ With sidelights
☒ Other side door w/ sidelights

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☒ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☒ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3693

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1889, 1940? ☐ Actual ■ Estimated Source: 1891 Sanborn map shows original section of building

■ Additions/modifications, specify dates: Bumped out to rear ca. 1910-1915. East front-gable section added sometime after 1937.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Associated with Taliaferro family (merchants)

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 7, LOT 6-10

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

■ A. Associated with events that have made a significant contribution to the broad pattern of our history;

■ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: One of the oldest extant houses in Round Rock. Associated with prominent merchant family.

Period(s) of significance: 1889-1970

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-9

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 209 West Bagdad Street

Owner/address LAND FUND I INC, PO BOX 759. ROUND ROCK,TX 78680

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Hipped-roof bungalow with shallow hip-on-gable front porch roof, boxed in with siding, vent. Likely 1.5 stories.

Porch has turned posts and balusters. Symmetrical front facade; 4 windows, center door. Wooden picket fence surrounds large back yard with shed.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☐ Gable
- ☒ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type composition
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☒ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☒ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 1/2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1440

3. Integrity

☒ Location ☒ Design ☐ Materials ☒ Workmanship ☒ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1910-1915 ☐ Actual ☒ Estimated Source: First appears on 1916 Sanborn Map

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Replaced previous house built ca. 1890 on lot but slightly to east of current building

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 2, LOT 14-15, 13 (E 15 FT) & PT VACATED ALLEY

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☒ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: One of the last remaining houses on large parcel. Along with other buildings on this block, helps to preserve 208 S. Blair on south half of block.

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☒ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-10

1. Identification

County Williamson City Round Rock

Current name Bjorge & Parker, PC (accountants) Historic name

Address 211 West Bagdad Street

Owner/address WEST, BAGDAD PARTNERSHIP, 17170 FM 487 BARTLETT,TX 76511

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description 1 or 1-1/2 story office building. Limestone veneer front facade with dark brick trim, Hardie siding rest of building. 3-car attached carport faces Brown Street.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other 3 car attached carport to rear, 5 parking spaces on site

☐ Archeological evidence of outbuildings, specify

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Handicapped access north side

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type Hardie
- ☒ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other vinyl

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☒ With transom
- ☒ With sidelights
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☒ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☒ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☒ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Stories: 1 or 1-1/2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1903

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☒ Other Was part of lot for 209 West Bagdad

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1999 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☒ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 2, LOT 11, 12 & 13 (12' OF)

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-11

1. Identification

County Williamson City Round Rock

Current name McConico Building Historic name _____

Address 301 West Bagdad Street #1

Owner/address CITY OF ROUND ROCK, 221 E. MAIN ST., ROUND ROCK,TX 78665

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Large building with block stone veneer, central hallway features peaked window-wall entry on front facade.

Rectangular windows 2nd floor with rect. and double, segmtl arched windows first floor. Slightly irregular footprint. Secondary entrance at rear.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other Street parking front/side of building; large parking lot to rear of building (down hill)

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Paver hardscaping at front and rear entries

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 4 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☒ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other aluminum

Doors:
- ☐ Single-door primary entrance
- ☒ Double-door primary entrance
- ☐ With transom
- ☒ With sidelights
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☒ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 27,800

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ■ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other City of Round Rock Offices and Municipal Court

5. Architectural History

Architect: _____ Builder: _____

Construction date: 2002 ■ Actual ☐ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Previously 5 small houses on this site

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): MUNICIPAL CENTER PH 1 (SECOND AMENDING PLAT), BLOCK A, Lot 1, ACRES 5.31

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-12

1. Identification

County Williamson City Round Rock

Current name Allen R. Baca Center Historic name

Address 301 West Bagdad Street #2

Owner/address CITY OF ROUND ROCK, 221 E. MAIN ST., ROUND ROCK,TX 78665

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Large senior citzens' center with secondary entry on Bagdad; main entrance faces rear of Building 2. Stone veneer. 2-story open entry lobby with arched awning and parapet. First floor window walls. Segmental arches also on top floor of parking garage.

Outbuildings (Specify number and type):

Garage att Barn _____ Shed _____ Other Parking garage attached to south side with entrance from Bagdad and rear parking lot

☐ Archeological evidence of outbuildings, specify

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other Flagpole to left (south) of main entrance

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 7 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☒ Fieldstone veneer
- ☒ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other metal frame

Doors:
- ☐ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 16069

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☒ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☒ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1960 ☐ Actual ☒ Estimated Source: WCAD

☒ Additions/modifications, specify dates: 8175 sq ft addition plus carport, 1986

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect ☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 10, LOT 1-5 & 13-16 & VAC ALLEY

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-13

1. Identification

County Williamson City Round Rock

Current name Vacant Historic name _____

Address 310 West Bagdad

Owner/address City of Round Rock, 221 East Main Street, Round Rock, TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): E. H. & A. Round Rock Joint Venture, Replat Of Lt 2, BLOCK 6, Lot 2A, ACRES 0.181

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-14

1. Identification

County Williamson City Round Rock

Current name Vacant - For Sale Historic name

Address 105 South Blair

Owner/address WILLIAM K & DOROTHY DTODD MGT TRST, ROUND ROCK LEADER, PO BOX 459, ROUND ROCK,TX 78680-0459

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Rectangular brick commercial building with central single-door main entry on west elevation, no windows.

Described on WCAD as a storage warehouse.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

5 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other No windows

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 8,060

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ■ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1970 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 8, LOT 11-15 S 50FT OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-15

1. Identification

County Williamson City Round Rock

Current name Franco House Historic name

Address 208 South Blair Street

Owner/address EMILIA IRENE CANTU FRANCO, 208 S BLAIR ST, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Small house with classic Greek Revival details including full height porch (south elevation), wide band of trim below cornice, side gables (east), round Doric columns. Center interior chimney. Low metal picket fence with stone posts (front), also chain link (rear).

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 3 Other carport with corrugated metal roof

☐ Archeological evidence of outbuildings, specify

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☒ Gardens ☐ Other pergola over seating area

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☒ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 1 Specify number(s)
- ☒ Interior
- ☐ Exterior
- ☒ Brick
- ☐ Stone
- ☒ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☒ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☒ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☒ Other 2 side porches (east)

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1666

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1881-1890 ☐ Actual ■ Estimated Source: Deed research; appears on 1891 Sanborn map

■ Additions/modifications, specify dates: Side (east) porches and additional gable wing were added between 1896-1902.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: By 1900, property included lots 1-10. Subdivided when lots 1-7 sold in 1952.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 2, LOT 1-7, ACRES .542

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

■ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

■ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: One of the oldest extant houses in Round Rock, includes large lot with garden as was common in early days of city.

Period(s) of significance: 1881-1952

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-16

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address No number, Brown Street between Main and Round Rock Avenue

Owner/address NAGLE HOLDINGS LP, 400 W MAIN ST STE 210, ROUND ROCK,TX 78664-5809

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): NAGLE SUB, BLOCK A, Lot 2

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-17

1. Identification

County Williamson City Round Rock

Current name Vacant Historic name First United Methodist Church of Round Rock

Address 110 South Brown Street

Owner/address CITY OF ROUND ROCK, 221 E MAIN ST, ROUND ROCK,TX 78665

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Former church building with sanctuary, classrooms and office space. Regular and raked brick veneer, fieldstone veneer, some painted plywood around windows. Has since been demolished.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☒ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other Handicapped access on east side via concrete ramp

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- ?___ Number of bays
- ☐ Stucco
- ☐ Stone
- ☒ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☒ Fieldstone veneer
- ☐ Awning(s)
- ☒ Other plywood

Chimneys:
- 0___Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☐ Single-door primary entrance
- ☒ Double-door primary entrance
- ☐ With transom
- ☒ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☒ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☒ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☒ Other verandah
☒ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 8168

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ■ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ■ Educational ☐ Government ■ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1958 ■ Actual ☐ Estimated Source: "Historical Round Rock," pp. 377-382

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Replaced previous wood-frame Methodist church on this site.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): E. H. & A. Round Rock Joint Venture, BLOCK 6, Lot 1, ACRES 0.318

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-18

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name

Address 120 South Brown Street

Owner/address CITY OF ROUND ROCK, 221 E MAIN ST, ROUND ROCK,TX 78665

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Brick veneer ranch home. Has since been demolished to make way for City transit center.

Outbuildings (Specify number and type):

Garage 2 att Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other Handicapped access east side

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☒ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☒ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☒ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☒ Fabricated metal
☒ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1737

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☒ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1956 ☒ Actual ☐ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☒ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): E. H. & A. Round Rock Joint Venture, Replat Of Lt 2, BLOCK 6, Lot 2B, ACRES 0.1492

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-19

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address 209 South Brown Street

Owner/address City of Round Rock, 221 East Main Street, Round Rock, TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ■ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Originally part of 208 South Blair property. Previously had small house on site.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 2, LOT N/PT 8-10

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-20

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address 211 South Brown Street

Owner/address City of Round Rock, 221 East Main Street, Round Rock, TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ■ Vacant ☐ Other Temporary construction office trailer

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Originally part of 208 South Blair property. Previously had small house on site.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 2, LOT 8-10 S 1/2 OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-21

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 110 Florence Street

Owner/address LEE R. PENA, JR., 110 FLORENCE ST, ROUND ROCK,TX 78664-5816

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Ranch with inset carport, peaked roof over front entry. Stacked fieldstone veneer, floor-to-ceiling windows on front facade. Chain-link fence. Dirt/gravel parking takes up most of front yard.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other Integrated carport

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☒ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☐ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☒ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1131

3. Integrity

☐ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 1, LOT 1 & 2 W 1/2 OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-22

1. Identification

County Williamson City Round Rock

Current name 106 South Harris Office Building (various professional offices) Historic name _____

Address 106 South Harris Street

Owner/address NAGLE HOLDINGS LP, 400 W MAIN ST STE 210, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Cross-gabled Craftsman bungalow; orig. garage converted to second entrance. Modern 2-story rear addition.

Main porch posts moved back from corners to make room for shortened concrete deck and enlarged sidewalk. Front is all hardscape, small side yard.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other 11 street parking spaces on Harris

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Handicapped access via concrete ramp - wood posts, metal rails

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type Hardiplank
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other Vinyl sash

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☒ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☒ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☒ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 5472

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ■ Estimated Source: 1992 Historic Resources Survey

■ Additions/modifications, specify dates: Two-story addition to rear, 2006

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 5, LOT 2-3

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ■ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-23

1. Identification

County Williamson City Round Rock

Current name Harris Street Center Historic name _____

Address 109 South Harris Street

Owner/address HCDG LLC, 400 W MAIN ST. STE #210, ROUND ROCK, TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Large 2 or 2.5 story office building in 2 sections with 1st & 2nd floor connectors and main reception/stair block.

Rubble-look fieldstone veneer with inset horizontal siding. Stacked stone square columns at corners. Metal awnings over 2nd floor windows.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Handicapped access west side (front elevation)

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3-1-3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type Hardie
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other multiple doors

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☒ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☒ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 or 2.5 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 8220

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 2007 ■ Actual ☐ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Previously a house was on this site.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK , BLOCK 6, LT 7&6pts, 8-10, 11-14pts & VAC ALLEY, ACRES .3605

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-24

1. Identification

County Williamson City Round Rock

Current name Round Rock Cafe Historic name

Address 110 South Harris Street

Owner/address NAGLE HOLDINGS LP, 400 W MAIN ST. STE 210, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Folk National cottage with addition/extension to left rear (south). New sidewalks and parking take up most of what was front yard.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Double concrete handicapped ramp with metal rails to front door

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other vinyl

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☒ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☒ Other pediment w/ brackets

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☒ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1768

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1910 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: Addition to rear/south

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 5, LOT 1, S/PT 2, ACRES .2274

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-25

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address No Number, IH-35 South

Owner/address City of Round Rock, 221 East Main Street, Round Rock, TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot, 2.036 acres

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ■ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): Wiley Harris Survey

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-26

1. Identification

County Williamson City Round Rock

Current name Parking lot Historic name _____

Address No Number North Lampasas (behind Main Street Grill)

Owner/address MORRIS & BROWN INVESTMENTS, 100 E MAIN AVE #201, ROUND ROCK,TX 78664-5243

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Parking lot

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Originally part of 208 South Blair property. Previously had small house on site.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 14 PT & 15 PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-27

1. Identification

County Williamson City Round Rock

Current name Corridor Development Consulting, Inc. Historic name Ice house

Address 107 North Lampasas Street

Owner/address HERMAN W CRICHTON, DBA CHRIGHTON & ASSOCIATES, 6448 E HIGHWAY 290, STE B105, AUSTIN,TX 78723-1038

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Stone building with stucco over front facade. Shed-roofed porch cover of standing seam metal supported by wo deck. Flat roof slopes slightly toward rear of building.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other 2 on-street parking spaces, 2 on-site parking spaces

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☒ Other Unknown

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☒ Stucco
☒ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other concrete deck

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1350

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1905 ☐ Actual ■ Estimated Source: First appears on 1909 Sanborn Fire Insurance Map

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 21, LOT 10 S 100 FT OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

■ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

■ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ■ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain Could be considered for addition to existing National Register district.

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-28

1. Identification

County Williamson City Round Rock

Current name Primera Iglesia Bautista (First Baptist Church) Historic name

Address 202 North Lampasas Street

Owner/address PRIMER IGLESIA BAUTISTA OF ROUND ROCK, PO BOX 1172, ROUND ROCK,TX 78680

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Brick church with gabled covered main entrance, also secondary entrance, both on east side. 4 vertical windows east side, plus circular window south side in gable. Steeple over main entrance.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other on site parking lot with six spaces

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☒ Other brick veneer

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other 2ndry single door entry

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☒ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☒ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3350

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1996 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Former Lodge Hall on this site in 1930s (Sanborn map notes "colored")

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 35, LOT 1 & 2 E 1/2

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-29

1. Identification

County Williamson City Round Rock

Current name Office building - For Sale Historic name

Address 110 South Lampasas Street

Owner/address MORRIS L. JOSEPH, 2633 OAK MEADOW DR., ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Commercial building with 4 offices. Fieldstone veneer below roofline, horizontal siding in gables. Gabled dormer over each entry. Each office has double door plus single one-over-one window. Standing seam galvanized metal roof overhangs front facade.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☒ Metal standing seam
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type Hardie (gables)
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other Four of these

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other Verandah, brackets

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 4080

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☒ Other House previously on this site

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 2009 ☒ Actual ☐ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect ☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____ *** Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 1 2 & 3

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-30

1. Identification

County Williamson City Round Rock

Current name City Parking Garage Historic name _____

Address 111 South Lampasas Street

Owner/address City of Round Rock, 221 East Main Street, Round Rock, TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Parking garage for City Hall and downtown. Concrete construction, 4 levels, vehicle entrance on Lampasas.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☒ Other No roof

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 4 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ■ Other Parking Garage

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1987 ■ Actual ☐ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 10, Lot 6-10 plus Vacant Alley

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-31

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 108 North Lewis Street

Owner/address BRUCE JONES, 2602 CORABELLA PL, CEDAR PARK,TX 78613

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Craftsman bungalow with hipped roof and front gable over inset porch. Original bracketed eaves no longer visible after roof changed from shingles to standing-seam metal. Prominent roof vent in front gable.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other Poss. former carriage house/garage converted to 2nd rental unit at rear of property.

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☒ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal standing seam - tan
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☒ Gable roof	☐ Fabricated metal
☒ Inset	☐ Spindlework
☒ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1266

3. Integrity

☒ Location ☐ Design ☒ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1935 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Currently a rental; second rental unit at rear of property facing East Liberty

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 19, LOT 10-12

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

■ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-32

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 101 East Liberty Street

Owner/address CITY OF ROUND ROCK, 221 E MAIN ST, ROUND ROCK, TX 78665

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Metal storage warehouse, set well back from street. No sidewalk or driveway to building. Lot is overgrown. Appears to be vacant/unused. Previously owned by Walsh family.

Outbuildings (Specify number and type):

Garage 0 Barn 0 Shed 0 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal corrugated
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- ____ Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type corrugated metal
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other no visible windows

Doors:
- ☐ Single-door primary entrance
- ☒ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☒ Other corrugated metal

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 5625

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ■ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: Unknown ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Jail was previously on this site from 1890s through at least 1930s.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ■ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 12

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ■ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-33

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address No Number East Liberty Avenue (between 101 and 107)

Owner/address CECELIO GONZALES ESTATE, C/O CONSUELO GONZALES, 220 S 1ST ST, LA PORTE, TX 77571-5109

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Originally part of 208 South Blair property. Previously had small house on site.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 13

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-34

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 102 East Liberty Street

Owner/address HAZEL DELORES EARL ESTATE Owner Address: % LEROY HOLIDAY III 102 E LIBERTY AVE ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Ranch home with gabled porch. Chain link fence.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☒ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Min Tradl

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☒ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☒ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other concrete porch deck

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1908

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ■ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 35, LOT 3

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-35

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address No Number East Liberty Avenue (between 102 East Liberty and church)

Owner/address PRIMER IGLESIA BAUTISTA OF ROUND ROCK, PO BOX 1172, ROUND ROCK,TX 78680

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Originally part of 208 South Blair property. Previously had small house on site.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 35, LOT 2 W 1/2

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-36

1. Identification

County Williamson City Round Rock

Current name Ben's Barber Shop Historic name _____

Address 107 East Liberty Street

Owner/address Joe Lee Johnson Estate, c/o MELLOWNIE JOHNSON 205 E AUSTIN AVE ROUND ROCK,TX 78664-5209

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Two room cabin with separate door for each room. Handicapped access on front (north) side with concrete ramp to west door, fabricated metal railing.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type T-111 type
- ☐ Fieldstone veneer
- ☒ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☒ Other two of these

Plan:
- ☐ L-plan ☒ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 160

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1970 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 14 PT & 15 PT, ACRES .0774

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-37a

1. Identification

County Williamson City Round Rock

Current name Cozy Corner (bar - Mellownie Johnson, owner) Historic name

Address 200 East Liberty Avenue (parcel is officially on Lampasas)

Owner/address JOE LEE JOHNSON ESTATE, c/o MELLOWNIE JOHNSON, 205 E AUSTIN AVE, ROUND ROCK,TX 78664-5209

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Property contains two buildings (see sheet 37b). Cozy Corner bar is a brick veneer building. Minimal parking in front (south) of building. Shed roof porch has composition shingles and is supported by plain posts/brackets.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☒ Other brick veneer

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other 2nd single entrance

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1400

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☒ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1960 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 36, LOT 5

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-37b

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 200 East Liberty Avenue (parcel is officially on Lampasas)

Owner/address JOE LEE JOHNSON ESTATE, c/o MELLOWNIE JOHNSON, 205 E AUSTIN AVE, ROUND ROCK,TX 78664-5209

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Property contains two buildings (see sheet 37a). This two-room house with rear shed addition has two front doors, porch with shed roof, wooden posts and deck. No curb cut, driveway or sidewalk to house. Appears to be vacant.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal corrugated
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type poss. T-111
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other brick veneer

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☒ Other two of these

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☒ Other Hall-and-parlor

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☒ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☒ Other corrugated metal

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1400

3. Integrity

☐ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ■ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1905 ☐ Actual ■ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: May have been moved to this lot from another location.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 36, LOT 5

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-38

1. Identification

County Williamson City Round Rock

Current name Vacant - For Sale Historic name

Address 201 East Liberty Street

Owner/address JOHN E. HORTON, 5201 RAINCREEK PKWY, AUSTIN,TX 78759

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Commercial office building with odd, truncated mansard-type roof (has green metal "shingles") that overhangs front facade and concrete sidewalk on north and west sides.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☒ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☒ Metal shingles over porch
☒ Other stand seam metal

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type B&B plywood
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other rear covered porch

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2051

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1970 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 21, LOT 10 N 25' OF & 11, ACRES .155

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-39

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address No Number East Liberty (between 200 and 206)

Owner/address DOUGLAS B. SHEWALTER, 1424 YORKSHIRE DR., AUSTIN,TX 78723

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☐ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- ____ Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- ____Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☐ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 36, LOT 4

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-40

1. Identification

County Williamson City Round Rock

Current name Vacant - former home of Joe Lee Johnson (deceased) Historic name

Address 206 East Liberty Street

Owner/address Mellownie Johnson, 205 East Austin Avenue, Round Rock, TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Center passage Folk National cottage with symmetrical front facade: two single-entry doors at center, flanked by a single window on each side. Hipped-roof porch with turned posts; shed-roofed addition to rear. Dog-ear picket fence across front of property.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type T-111 type
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☒ Other two front doors

Plan:
- ☐ L-plan ☒ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☒ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☒ Wood posts	☒ Jig-sawn trim
☐ Brick piers	☒ Other dog-ear frieze
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 644

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☒ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1900 ☐ Actual ☒ Estimated Source: WCAD, first appears on 1902 Sanborn map.

☒ Additions/modifications, specify dates: Porch added between 1909-1916. Shed addition to rear added sometime after 1937.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☒ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☒ Neglect ☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): City of Round Rock, Block 36, Lot 3

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☒ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: One of only a few buildings of this type still extant in Round Rock.

Period(s) of significance: 1900-1970

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☒ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-41

1. Identification

County Williamson City Round Rock

Current name Alite Laser Hair Removal Historic name

Address 208 East Liberty Street

Owner/address KYLE R. HUMPHRIES & DEBRA R. SPELLINGS, 209 WHITETAIL LN, HUTTO,TX 78634-5029

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Minimal traditional bungalow has been covered with stained pine siding (above) and corrugated metal (below). Shutters and door with diamond cut-out pattern have been removed. Fabricated metal porch supports replaced with round pine poles.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Min. Tradl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☒ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 1 Specify number(s)
- ☒ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☒ Stuccoed
- ☒ Other with cap

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☒ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☒ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 616

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 36, LOT 2

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-42

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 210 East Liberty Street

Owner/address JOE LEE JOHNSON ESTATE c/o MELLOWNIE JOHNSON, 205 E AUSTIN AVE, ROUND ROCK,TX 78664-5209

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Folk National gable-front-and-wing cottage with rear addition. One-care detached garage behind house with driveway to Sheppard Street. Building is in poor condition with visible structural damage.

Outbuildings (Specify number and type):

Garage 1 det. Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal standing seam (blue)
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type T-111 type
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☒ Other brick veneer 3 sides

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☒ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☒ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☒ Other Doric columns
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 914

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1905 ☐ Actual ☒ Estimated Source: First appears on 1909 Sanborn map

☒ Additions/modifications, specify dates: Rear addition between 1925 and 1937

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☒ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☒ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 36, LOT 1

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☒ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☒ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-43

1. Identification

County Williamson City Round Rock

Current name Parking Lot Historic name _____

Address No Number East Liberty Avenue (300 block)

Owner/address JOE LEE JOHNSON ESTATE, c/o MELLOWNIE JOHNSON, 205 E AUSTIN AVE, ROUND ROCK,TX 78664-5209

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Parking lot on opposite corner from Public Library

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☐ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- ____ Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- ____Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☐ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 37, LOT 7 & 6/S PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-44

1. Identification

County Williamson City Round Rock

Current name Barber shop Historic name

Address 301 East Liberty Avenue

Owner/address VINCENT SANCHEZ, 204 E ANDERSON AVE., ROUND ROCK, TX 78664-5204

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description This appears to be third and fourth additions to Kuno's Bar (109 North Sheppard). 3rd addition is gabled and faces Sheppard with its own entrance. 4th addition extends a flat roof to rear of 3rd addn, but fronts East Liberty with a separate entrance.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ■ Other on-site parking

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	■ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

- ■ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ■ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:

- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ■ Metal corrugated
- ☐ Other _____

Construction:

- ■ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:

- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ■ Siding, type T-111
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:

- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:

- ☐ Fixed
- ☐ Wood sash
- ■ Double hung
- ☐ Casement
- ■ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:

- ■ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:

- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ■ Rectangular
- ☐ Other _____

Foundation:

- ■ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 4583

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 20, LOT 10

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-45

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 305 East Liberty Street

Owner/address EQUITY TRUST COMPANY, 12444 RESEARCH BLVD, AUSTIN,TX 78759

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Folk National cottage, two-room original building with full-width rear addition. Shed roof over full-width front porch. Rusty standing-seam metal roof on original section, shingles on rear addition. Grass driveway to west, no garage or carport.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other overgrown gravel driveway

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal standing seam (galv.)
- ☒ Other shingles on rear addn.

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type vinyl
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☒ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☒ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☒ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☒ Other concrete porch deck

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 720

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1910-1195 ☐ Actual ■ Estimated Source: First appears on 1916 Sanborn Map

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Current building replaced original circa-1900 dwelling

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ■ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 20, LOT 11

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ■ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-46

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 306 East Liberty Street

Owner/address MAMIE LEE TISDALE BAILEY, 306 E LIBERTY AVE., ROUND ROCK,TX 78664-5241

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Buff brick gable-front house with inset front entrance. One-car detached garage to rear with concrete driveway. Chain link fence around back yard.

Outbuildings (Specify number and type):

Garage 1 det. Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Brick planters flank sidewalk to front door.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Min. Tradl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☒ Other brick veneer

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☒ Fabricated metal
☒ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 846

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☒ Setting ☒ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 37, LOT 3

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-47

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 307 East Liberty Street

Owner/address MELLOWNIE JOHNSON, 205 E. AUSTIN AVE ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Gable-front bungalow with front-gable roof over concrete porch deck on west side of front facade.

Front yard enclosed with tall chain-link fence.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type T-111 type
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- ____Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☒ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☒ Gable roof	☒ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☒ Other concrete deck
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 536

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☒ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ■ Estimated Source: WCAD (does not appear on 1937 Sanborn map)

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 20, LOT 12

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: 1940-1970

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain Would be a contributing structure in a district.

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-48

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 308 East Liberty Street

Owner/address CAROL J. CALDERONI, 11 COLONIAL ROW DR., THE WOODLANDS, TX 77380

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Minimal Traditional L-plan house with inset porch. New siding, garage has been converted to room with single entry door. Concrete handicapped ramp to front door with tubular metal railing.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Min. Tradl.

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other 2nd single door

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☒ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Plan:

☒ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1344

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 37, LOT 2

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-49

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 309 East Liberty Street

Owner/address JOE DOUGLAS JOHNSON, 309 E LIBERTY ST, ROUND ROCK,TX 78664-5240

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Possible duplex converted to single-family home or vice versa? Two front doors (not same size), odd roof lines. Might be a gable-front-and wing with infilled front porch and then new full-width gabled porch covering added later.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other Carport (possibly circa 1960s)

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ■ Other grass driveway

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	■ Other Folk Natl.

Structural Details:

Roof Type:
- ■ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ■ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ■ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ■ Siding, type T-111 type
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ■ Wood sash
- ■ Double hung
- ☐ Casement
- ■ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ■ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ■ Other 2nd single-door entry

Plan:
- ■ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ■ Pier and beam
- ■ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ■ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ■ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ■ Other concrete deck

Stories: 1 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 950

3. Integrity

■ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ■ Estimated Source: WCAD (not on 1937 Sanborn map)

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 20, LOT 13 & 14

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ■ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-50

1. Identification

County Williamson City Round Rock

Current name Casa Sesamo Child Care Historic name

Address 310 East Liberty Street

Owner/address J. CALDERONI & ASSOCIATES INC., 11 COLONIAL ROW DR., THE WOODLANDS, TX 77380

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Gable-roof house with inset central entry door, asymmetrical facade with single window on right and double on left.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Handicapped access on south side, sidewalk slopes to porch

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type Hardie
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☒ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1322

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1990 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 37, LOT 1

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-51

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address 311 East Liberty Avenue

Owner/address JOHN S. AVERY, Sr., 2803 PECOS ST AUSTIN,TX 78703-1144

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 20, LOT 15

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-52

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address 401 East Liberty Avenue

Owner/address JOHN S. AVERY, Sr., 2803 PECOS ST AUSTIN,TX 78703-1144

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot. House was moved.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 19, LOT 7, W/PT 8

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-53

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address 402 East Liberty Avenue

Owner/address THELMA WOODS, 1209 S MAYS ST., ROUND ROCK,TX 78664-6729

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: House extant in 1992 survey was moved or demolished.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 38, LOT 5

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-54

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address 406 East Liberty Avenue

Owner/address MAMIE LEE TISDALE BAILEY, 306 E LIBERTY ST., ROUND ROCK,TX 78664-5241

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 38, LOT 4

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-55

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address 408 East Liberty Avenue

Owner/address MAMIE LEE TISDALE BAILEY, 306 E LIBERTY ST., ROUND ROCK,TX 78664-5241

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: House extant in 1992 survey was moved or demolished.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 38, LOT 3

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-56

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address 409 East Liberty Street

Owner/address JOHN S. AVERY, SR., 400 E MAIN ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot. House was moved.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 19, LOT 9, E/PT 8

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-57

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 410 East Liberty Street

Owner/address H. DAVID ZAVALA, SR. 410 E LIBERTY ST, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Minimal Traditional house has been veneered with fieldstone. Roof overhangs porch and is supported by square columns wrapped in same fieldstone.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 2 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Min. Tradl.

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

1 Specify number(s)
☐ Interior
☒ Exterior
☐ Brick
☒ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☒ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1900

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1984 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: According to the owner, the stone work was done by his father.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 38, LOT 2

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-58

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 412 East Liberty Street

Owner/address JAMES R. & AMADAY D. ZAVALA, 2002 VIVIAN DR., ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Brick veneer house with two-story octagon rooms, side porch, and one-story rear addition. Significantly altered since 1992 survey.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Eclectic

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☒ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☒ Other veneer over stone?

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☒ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☒ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other Archway to front door

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1920

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1992 ☐ Actual ■ Estimated Source: WCAD (photos are included in the 1992 survey)

■ Additions/modifications, specify dates: 300 sq ft addition in 2000 per WCAD; brick veneer is not original?

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 38, LOT 1

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-59

1. Identification

County Williamson City Round Rock

Current name Jorge's Hair Design Historic name _____

Address 103 West Liberty Street

Owner/address GEORGE & ROSE M. BELTRAN, 103 W LIBERTY ST ROUND ROCK,TX 78664-5121

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Craftsman bungalow with decorative woodwork in front gable peak. Hipped roof with front gable over inset porch. May have originally had detached garage; driveway is extant. Shed roof cover over rear carport is supported by solid frame wall.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other Carport

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ■ Other Handicapped ramp on north side, wood ramp and handrails

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	■ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ■ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ■ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ■ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ■ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ■ Double hung
- ☐ Casement
- ■ Aluminum sash
- ☐ Decorative screenwork
- ■ Other solar screens

Doors:
- ■ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ■ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ■ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ■ Gable roof
- ■ Inset
- ■ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1334

3. Integrity

■ Location ■ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 23, LOT 11 PT & 12

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

■ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-60

1. Identification

County Williamson City Round Rock

Current name Vacant Lot - was Casas home Historic name _____

Address 105 West Liberty Street

Owner/address MICHAEL JOSEPH, 2202 PARKLAND CV, ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant Lot

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1334

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Folk National cottage on site was moved.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 23, LOT 10 N PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-61

1. Identification

County Williamson City Round Rock

Current name Reid's Cleaners & Laundry Historic name Former site of John C. Halton House

Address 303 West Liberty Avenue

Owner/address REID-CLIFFORD ROUND ROCK LP, 303 W LIBERTY AVE, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description New concrete block construction with 4 oversized dormers, vent stacks, drive through; primarly entrance faces away from Round Rock Avenue and into parking lot. Blue commercial standing seam metal roof.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other on-site parking lot with approx. 20 spaces

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☒ Dormers:
- ☒ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☒ Metal blue standing seam
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☒ Other CMU

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☒ Other CMU

Chimneys:

1 Specify number(s)
☒ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☒ Other metal

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☐ Wood posts
☐ Brick piers
☒ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other CMU columns

Stories: 1-1/2? **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3500

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1998 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Replaces 2-story house extant on this site during 1992 survey

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 25, LOT 13-15

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-62

1. Identification

County Williamson City Round Rock

Current name Karen Price, PC (acct) -- Professional Massage Associates Historic name _____

Address 305 West Liberty Street

Owner/address KLAERNER INVESTMENT CO. LLC, 305 W LIBERTY ST, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Hall-and-parlor style Folk National cottage with board-and-batten siding, newer standing-seam metal roof.

Porch with turned posts is not original. Two additions to rear of house, one with gable roof, one with shed roof.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 small Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☒ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal standing seam (blue)
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 4 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood bd&batten
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other vinyl

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☒ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☒ Perimeter wall
- ☐ Other _____

Porches:

☒ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☒ Spindlework
☒ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1248

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1915 ☐ Actual ☒ Estimated Source: First appears on 1916 Sanborn map

☒ Additions/modifications, specify dates: On 1916-1937 maps, has a front gable section to west where driveway is now -- possible garage?

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 25, LOT 12 & E/PT OF 11

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☒ Medium ☐ Low

Explain Although porch and roof have been altered, these changes are reversible.

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-63

1. Identification

County Williamson City Round Rock

Current name Dr. Keith Acheson DDS, Family and Cosmetic Dentistry Historic name _____

Address 309 West Liberty Avenue

Owner/address KEITH R. ACHESON, 309 W LIBERTY AVE., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Highly altered Folk National cottage with Queen Anne-style bay window on west elevation, all covered with stucco. Roof sheds down to new rear addition on west side to create covered walkway. Porch has concrete deck, oversized classical columns.

Outbuildings (Specify number and type):

Garage 1 det. Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Stone block walls create courtyard, screens.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other solar screens

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☒ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other concrete deck

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1196

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ■ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1910 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: Original board and batten structure enlarged and covered in stucco. New roof, porch, rear addition.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 25, LOT 10 & 11/PT W 1/2 OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-64

1. Identification

County Williamson City Round Rock

Current name Golden Chick Restaurant offices Historic name _____

Address 404 West Liberty Street

Owner/address W G G INTEREST INC, 2405 HEIGHTS BLVD., TAYLOR, TX 76574

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Two small side-gable cottages connected with flat roof. Front faces W. Liberty, back faces Round Rock Ave.

Front has door, single sash window, double sash window, small front porch. Rear has center door, double sash window, attached 1-car garage.

Outbuildings (Specify number and type):

Garage 1 att. Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☒ Well/cistern ☐ Gardens ☒ Other Both front and back yards are all paved parking.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type alum or asbestos
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☒ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1440

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1945 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ■ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 31, LOT 4 PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ■ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-65

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 407 West Liberty Avenue

Owner/address JOHN E. & LINDA HENRY, 3500 BRUSHY CREEK RD., CEDAR PARK,TX 78613-4119

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Buff brick veneer L-plan ranch. Bank of four casement windows in ell feature diamond pattern muntins, flanked by decorative shutters. Roof overhangs inset porch in crook of ell. Large living room window faces street.

Outbuildings (Specify number and type):

Garage 1 Barn _____ Shed _____ Other 2 car detached garage with flat roof and wood siding

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other 7 New diagonal concrete parking spaces in front, 1 handicapped

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☒ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☒ Other brick veneer

Chimneys:
- 1 Specify number(s)
- ☒ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☒ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other diamond pattern muntin

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☒ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☒ Fabricated metal
☒ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2354

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1955 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): City Of Round Rock, BLOCK 26, Lot 13-15

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-66

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 409 West Liberty Street

Owner/address E. J. WALSH, Jr. 405 ROUND ROCK AVE, ROUND ROCK,TX 78664-5143

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Irregular bungalow with stone veneer, rear addition with composition siding. Breezeway between house and Garage with wood beadboard siding. Garage was originally detached; 2-car, 1 door + workshop with window (?)

Outbuildings (Specify number and type):

Garage 1 det. Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Approx. 12 parking spaces on street

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other storm windows

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☒ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 1/2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1746

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ☒ Estimated Source: WCAD

☒ Additions/modifications, specify dates: Breezeway between house and garage, date unknown

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): City Of Round Rock, BLOCK 26, Lot 6-9 PTS OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☒ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☒ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☒ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-67

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 410 West Liberty Street

Owner/address CONSTANCE U. PARK, 411 PALOS VERDES DR., AUSTIN,TX 78734

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Minimal Traditional house with some board & batten siding, bracketed eaves, inset porch, attached garage.

Also synthetic siding (east half) and fieldstone veneer over lower front center section (near front door). Chain link fence surrounds yard.

Outbuildings (Specify number and type):

Garage 1 att. Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Min. Tradl.

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☒ Other bracketed eaves

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☒ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1238

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 31, LOT 8-9

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-68

1. Identification

County Williamson City Round Rock

Current name Baker-Aicklen & Associates (engineers) Historic name

Address 507 West Liberty Avenue

Owner/address JOE M. BAKER, 959 BLUE SPRING CV, ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Commercial building, stucco. Four bays; three with single fixed two-light window, fourth with entry door.

Arch above entry with decorative lights on either side, large decorative quoins on outside corners and flanking outermost windows.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Parking lot in front of building. Gated lot.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☒ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☒ Metal standing seam
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other Arched door opening

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 5003

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1998 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Building replaces house on this site, extant during 1992 survey.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): OLSON SUB, BLOCK A, LOT 1

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-69

1. Identification

County Williamson City Round Rock

Current name TX Open Door Realty #102/Energy Systems Associates #201 Historic name Round Rock Broom Factory

Address 100 East Main Street

Owner/address MORRIS & BROWN INVESTMENTS, 100 E MAIN AVE #201, ROUND ROCK,TX 78664-5243

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☒ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Italianate two-part commercial block building, limestone with four wooden double doors set into half-round arched openings on ground floor. Four tall 4-over-4 windows on second floor with segmentally arched hoods with center keystone. Stepped parapet.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☒ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☐ Stucco
☒ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☒ Awning(s)
☒ Other Cloth awnings

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other Two primary entrances

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 4800

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1880 ☐ Actual ☒ Estimated Source: 1992/1996 surveys

☒ Additions/modifications, specify dates: Left arched support removed in 1920s for auto repair shop and then reconstructed in 1980s restoration.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Built by R.D. Harris & W.A. Taliaferro as a grocery store. Broom Factory 1900-1911.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 9

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☒ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☒ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: Contributing to existing National Register district.

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-70

1. Identification

County Williamson City Round Rock

Current name Quinn's (bar) Historic name Koppel's General Store

Address 101 East Main Street

Owner/address SARAH N. ROBERTS, 402 E MAIN AVE., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial block building, ashlar limestone, flat parapet. Three sets of wooden double doors on N (front) facade. One double door plus bumped-out window wall on W elevation. French door at rear of building, W side.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☐ Frame
- ☐ Adobe
- ☐ Solid brick
- ☒ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☒ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☐ Single-door primary entrance
- ☒ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2400

3. Integrity

☒ Location ☐ Design ☒ Materials ☒ Workmanship ☐ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1876 ■ Actual ☐ Estimated Source: "Historical Round Rock", page 257

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division; National Register district listing

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 11 N 80 FT OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-71

1. Identification

County Williamson City Round Rock

Current name BWM Group Architects Historic name Otto Reinke Building (City Bakery)

Address 102 East Main Street

Owner/address BILLY L. & JANET F. HUGGINS, 26 WOODLAND LN, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☒ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Limestone Italianate two-part commercial block building. Oversized, arched center main entrance with modern deep-inset doorway; window above is similarly sized. Flanked by smaller windows above; similarly sized arched openings below with infilled windows.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☒ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☒ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☒ Awning(s)
☒ Other cloth awnings

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other single lite per window

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3576

3. Integrity

☒ Location ☐ Design ☒ Materials ☒ Workmanship ☐ Setting ☐ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1879 ☐ Actual ☒ Estimated Source: WCAD, 1992 survey

☒ Additions/modifications, specify dates: Gutted by fire 1963; vacant until 1970. Restored by architect Martin S. Kermacy.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 8

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-72

1. Identification

County Williamson City Round Rock

Current name O'Barr Rost Realtors Historic name

Address 103 East Main Street

Owner/address O'BARR H. ROST, 103 E MAIN ST., ROUND ROCK,TX 78664-5242

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Coursed stone one-part commercial block building. Segmental arched block headers with keystones over two large windows and one center double entry door. Transoms are bisected vertically. Current awning attached at top of door, bottom of transom.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☐ Frame
- ☐ Adobe
- ☐ Solid brick
- ☒ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☒ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☒ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☒ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other segmtl arched transoms

Doors:
- ☐ Single-door primary entrance
- ☒ Double-door primary entrance
- ☒ With transom
- ☐ With sidelights
- ☒ Other segmtl arched transom

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2400

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1876 ☐ Actual ☒ Estimated Source: WCAD

☒ Additions/modifications, specify dates: ca. 1900, original stone facade collapsed and was replaced with wooden storefront

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Grocery, drug, and notions store 1880s; Walsh TV & Appliances 1950s.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 12

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-73

1. Identification

County Williamson City Round Rock

Current name AGAPE Pregnancy Resource Center Historic name

Address 104 East Main Street

Owner/address AGAPE PREGNANCY RESOURCE CENTER, 104 E MAIN ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☐ Yes ☒ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One part commercial block building with stepped parapet. Storefront is asymmetrical; left 3/5 includes off-center door with sidelights, flanked by window walls on fieldstone bases. Rest of storefront has large floor-to-ceiling display window plus oval window.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☐ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☒ Other unknown

Wall Facade:
- 2 Number of bays
- ☒ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☒ Awning(s)
- ☒ Other awning with balustrade

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other display, window wall

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☒ With sidelights
- ☒ Other diamond pattern muntins

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1953

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1947 ■ Actual ☐ Estimated Source: "Historical Round Rock," page 261

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Previous building on site built ca. 1876

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 7, PT 6

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-74

1. Identification

County Williamson City Round Rock

Current name Energy Systems Associates Historic name Pennington Jewelry Store

Address 105 East Main Street

Owner/address MORRIS & BROWN INVESTMENTS (O0318591) 100 E MAIN AVE #201 ROUND ROCK,TX 78664-5243

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Limestone Italianate one-part commercial building. Three equally-sized double doors in front facade with segmentally arched, three-lite transoms above. Shallow stone corbelled parapet. Metal posts with connecting chains in front of doors.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☒ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☒ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other No front windows

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☐ With sidelights
☒ Other Three of these

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3131

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1910 ☐ Actual ☒ Estimated Source: WCAD (1992 Survey lists as 1876)

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 13

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-75

1. Identification

County Williamson City Round Rock

Current name (Space for Lease) Historic name Jackson Building

Address 108-110 East Main Street

Owner/address Palmer Investments LP, 110 East Main Street Round Rock, Texas

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☐ Yes ☒ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial block building with decorative parapet. Two identical storefronts; each with an inset double entry door with sidelights flanked by display window walls. Transom windows over each storefront are extant.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other window walls

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 4575

3. Integrity

☒ Location ☒ Design ☐ Materials ☒ Workmanship ☐ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ■ Estimated Source: 1992 Survey; WCAD lists as 1931

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Possibly constructed 1880 and modified 1930.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 5 & 6/E PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-76

1. Identification

County Williamson City Round Rock

Current name Vacant Historic name Stockbridge Grocery Store

Address 109 East Main Street

Owner/address MABEL O. MONTEITH LIVING TRUST c/o MABEL & GEORGE MONTEITH, 1731 STRATFORD RD., FAYETTEVILLE,NC 28304

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part ashlar limestone commercial block building with two arched entryways. Straight parapet with finials at corners. Each archway is filled in to spring point, with 3-over-3 lite single entry door flanked by sidelights. Infill wood above doors has dec. moldings.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☐ Frame
- ☐ Adobe
- ☐ Solid brick
- ☒ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☒ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other None

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☒ With sidelights
- ☒ Other two of these

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1680

3. Integrity

☒ Location ☐ Design ☒ Materials ☐ Workmanship ☒ Setting ☐ Feeling ☒ Association

4. Function

D-76

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1910 ☐ Actual ☐ Estimated Source: WCAD

☒ Additions/modifications, specify dates: Entry doors have been updated

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect ☐ Development ☒ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT W 19' OF 14

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-77

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 111 East Main Street

Owner/address MIKE & DORIS ECKERT, 309 OLD SAN ANTONIO RD., FREDERICKSBURG,TX 78624-6118

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial block building. Mostly (not entirely) coursed ashlar limestone blocks of varying sizes.

Central double door, infilled transom. One single-lite window on either side of door; possible replacements for double-hung windows. Straight parapet.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☒ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2478

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1910 ☐ Actual ☐ Estimated Source: WCAD

☒ Additions/modifications, specify dates: Transom above door appears to be covered with wood; windows have been replaced.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT PTS 14-15

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-78

1. Identification

County Williamson City Round Rock

Current name Main Street Sweets and Three Doors Art Gallery Historic name Round Rock Leader (1936-1984)

Address 112 East Main Street

Owner/address CADEN INCORPORATED (O0413499) 306 E MAIN ST STE #101 ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial block building of coursed ashlar limestone. Three double wooden entry doors, all with half-round transoms set into arched stone openings (no keystone). Each transom is bisected with slender muntins to create 4 equal wedges.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☒ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other None

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☐ With sidelights
☒ Other three of these

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1590

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1881 ■ Actual ☐ Estimated Source: "Historical Round Rock," page 261 (1881 per WCAD)

■ Additions/modifications, specify dates: Originally divided into two stores (from 1896-1902 and again from 1909-1936)

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Drug store and telephone exchange between 1909 and 1920s-30s

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 4

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-79

1. Identification

County Williamson City Round Rock

Current name The Cutting Edge Advanced Armorment (gun shop) Historic name

Address 113 East Main Street

Owner/address TRAVIS DALE & EDELGUNDE A. A. JOHNSON, P.O. BOX 218, ROUND ROCK,TX 78680-0218

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ■ NR District (Is property contributing? ☐ Yes ■ No) ☐ RTHL ☐ HTC ☐ SAL ■ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial block building. Facade consists of 4 columns (2 wide outer, 2 narrow inner) with 3 inset sections separating the columns. Each inset section has wood cover over top half; lower half is window wall. Modern full-height glass double entry door.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

■ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
■ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

■ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
■ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
■ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
■ Other window wall

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

■ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
■ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
■ Rectangular
☐ Other _____

Foundation:

■ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 779

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1920 ☐ Actual ■ Estimated Source: "Historical Round Rock," page 258

■ Additions/modifications, specify dates: Window walls, slipcover on facade

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect ☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 15 (19' OF)

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-80

1. Identification

County Williamson City Round Rock

Current name Star Co. Coffee Historic name Texas Power and Light Co., Bo-Kay Florist

Address 114 East Main Street

Owner/address CADEN INCORPORATED, 306 E MAIN ST. STE #101, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☐ Yes ☒ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story commercial building with flat parapet; facade features narrow coursed fieldstone veneer. Inset entry with display windows and two single-entry doors reflect previous use as a divided storefront for two businesses.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☒ Other unknown

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other Display

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other Two single doors

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2530

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☒ Setting ☐ Feeling ☒ Association

4. Function

D-80

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1882 ☐ Actual ■ Estimated Source: Historic building placard at Planning Department

■ Additions/modifications, specify dates: Stone facade is not original.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: May have been site of Miller's Exchange Bank, the target of Sam Bass and his gang

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 3

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

■ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: Building previously housed a grocery store (1885-1899), then a series of businesses: shoemaker (1896); harness saddlery and printing office (1902); drugstore and barbershop (1909); gentleman's furnishings (1916). Texas Power and Light from 1929-1969, then Bo-Kay Florist from 1969-1999.

Period(s) of significance: 1882-1969

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain Retains historical inset entrance with display windows and two single-entry doors, reflecting previous use as a divided storefront for two businesses.

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-81

1. Identification

County Williamson City Round Rock

Current name Hendrix Consulting Engineers Historic name McDonald Drug Store

Address 115 East Main Street

Owner/address BURKLEY J. HENDRIX, 115 E. MAIN ST., ROUND ROCK,TX 78664-5242

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial block building. Coursed limestone block w/ smaller stone veneer below display windows.

Top half of facade slipcovered with horizontal wood siding. Standing seam metal awning over 3-part display window w/3 transoms and double door.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☒ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type 2ood
☒ Fieldstone veneer
☒ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other 3 five-lite transoms

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2400

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1885 ☐ Actual ☒ Estimated Source: "Historical Round Rock," page 258; 1910 per WCAD

☒ Additions/modifications, specify dates: Original openings have been replaced; metal slipcover, later wood, was added over cornice

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☒ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 16

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-82

1. Identification

County Williamson City Round Rock

Current name Huggins/Seiler & Associates Engineers; also Creative Fire Historic name The Rock Theatre

Address 116 East Main Street

Owner/address HUGGINS-THREE, LP, 116 E MAIN ST, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ■ NR District (Is property contributing? ■ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ■ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story, brick surrounds stone inset on front facade. Double main entry door with one tall 8-lite window on either side and four 4-lite windows space evenly across tall windows and door. Stone band below parapet, similar to 118 East Main next door.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

■ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	■ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
■ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
■ Other unknown

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
■ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
■ Other Brick veneer

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

■ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
■ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
■ Rectangular
☐ Other _____

Foundation:

■ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 6000

3. Integrity

■ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ■ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1879 ■ Actual ■ Estimated Source: WCAD; historic building placard info at Planning Department

■ Additions/modifications, specify dates: Brick facade added ca. 1920. Retains sloping floor but awning and inset entryway/ticketbooth are gone.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Originally two storefronts; converted to City's first permanent theater, 1939-1969.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 2

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

■ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: Round Rock's first permanent movie theater, in operation from 1939 to 1969 as The Rock Theatre.

Period(s) of significance: 1939-1969

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-83

1. Identification

County Williamson City Round Rock

Current name Envy Salon Historic name "The Fair"/Walsh Company Store; Pettersen's Grocery

Address 117 East Main Street

Owner/address MONTEITH, KEVIN D (O422149) 8442 FERN BLUFF AVE ROUND ROCK,TX 78681-3541

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ■ NR District (Is property contributing? ■ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ■ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial block building. Coursed ashlar limestone with stepped parapet. Original inset double entry flanked by large display windows. Transom of 3 lites over each window and one wide lite over door. Flat stone header over transom. Awning.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

■ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	■ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ■ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☐ Frame
- ☐ Adobe
- ☐ Solid brick
- ■ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ■ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ■ Awning(s)
- ■ Other cloth awning

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ■ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☐ Single-door primary entrance
- ■ Double-door primary entrance
- ■ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ■ Rectangular
- ☐ Other _____

Foundation:
- ■ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3710

3. Integrity

■ Location ■ Design ■ Materials ■ Workmanship ■ Setting ■ Feeling ■ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1885 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: 45' addition to rear of building in early 1890s

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 17

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-84

1. Identification

County Williamson City Round Rock

Current name Main Street Grill (restaurant) Historic name Farmers State Bank, First National Bank

Address 118 East Main Street

Owner/address R. R. LEWIS PROPERTIES LTD, 1102 MARTIN AVE, ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Front elevation includes single course of stone between storefront and parapet. Intricate brickwork on facade. Double door main entry flanked on either side by one wood sash 16-over-1 window. Five sets of double windows along east side of building.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Handicapped access at front door

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☒ Other unknown

Construction:

☐ Frame
☐ Adobe
☒ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☒ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other 16 over 1

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3357

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: Farmers State Bank

Construction date: 1920 ☒ Actual ☐ Estimated Source: Historic building placard at Planning department

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Original two-story on this site in 1880 with store below, Opera House above. Fire 1916.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 1

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☒ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☒ Yes ☐ No

10. Priority (See manual for definitions.) ☒ High ☐ Medium ☐ Low

Explain One of the best-preserved commercial buildings in Round Rock; this former bank retains its vault, which is now used for dining.

The night-deposit box also remains (on east side of building). Brick masonry work on front facade reflects a high level of craftsmanship.

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-85

1. Identification

County Williamson City Round Rock

Current name Junior's (bar) Historic name Montedonico Bldg; Alcove Ice Cream Parlor (1920s)

Address 119 East Main Street

Owner/address KATHI & KEVIN MONTEITH, 8442 FERN BLUFF AVE., ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commerical block building. Stucco over stone; headers over windows and frame at top of pediment painted blue. 4 equal-width openings: 1 for door w/sidelight, 3 windows. Single-lite transom above each w/ wood divider. Left window enclosed below.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☒ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☒ Awning(s)
☒ Other Metal awning

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other Display

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1500

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ☒ Estimated Source: WCAD

☒ Additions/modifications, specify dates: Stucco; windows and doors are replacements.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☒ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 18

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-86

1. Identification

County Williamson City Round Rock

Current name Kelley Cleaners Historic name Carrington Building; Kelleys Dry Cleaners since 1957

Address 121 East Main Street

Owner/address ROBERT KIP LEWIS, 8013 MANITOU SPRINGS CT, AUSTIN,TX 78717

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial building; regular ashlar stone masonry with flush mortar joints. Larger door and window openings have been infilled with plywood to fit modern door and windows.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☒ Other Unknown

Construction:
- ☐ Frame
- ☐ Adobe
- ☐ Solid brick
- ☒ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☒ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other vinyl

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☒ With transom
- ☐ With sidelights
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☒ Perimeter wall
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3000

3. Integrity

☒ Location ☐ Design ☒ Materials ☐ Workmanship ☒ Setting ☐ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: Unknown Builder: Unknown

Construction date: 1882 ☐ Actual ☒ Estimated Source: WCAD

☒ Additions/modifications, specify dates: Originally two stories; modification date unknown

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Was a hardware store, drug store, meat market 1882-1916; grocery store 1916-1957.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☒ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 19

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☒ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-87

1. Identification

County Williamson City Round Rock

Current name Louisiana Longhorn Cafe 200-B/Susan Hart Boutique 200-A Historic name Anderson-Nelson Co. Building/R. R. Mercantile

Address 200 East Main Street

Owner/address MARJORIE B. QUICK/E&M QUICK LIVING TRUST, c/o DON QUICK, 1000 N. IH-35, STE. A, ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Cast-iron facade with pressed-time cornice. Two storefronts; one with corner entrance. Inset wooden double doors; window walls with fieldstone veneer below. Corrugated metal awning covers entire storefront. Connected to 204 East Main. Slopes away to rear.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☒ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☒ Awning(s)
☒ Other cast iron/pressed tin

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other window wall

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☐ With sidelights
☐ Other two of these

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☐ None ☒ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☒ Location ☒ Design ☐ Materials ☒ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1900 ☒ Actual ☐ Estimated Source: RTHL Marker

☒ Additions/modifications, specify dates: Building burned in 1985 but facade was not damaged; reopened 1986.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Mercantile company associated with prominent Swedish families of the area

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 21, LOT 7-8 PTS

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-88

1. Identification

County Williamson City Round Rock

Current name Bella Notte Historic name J. A. Nelson Company Building

Address 201–203 East Main Street

Owner/address CASEY FAMILY INVESTMENTS LLC, 1205 SAM BASS RD. STE #305, ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ■ NR District (Is property contributing? ■ Yes ☐ No) ■ RTHL ☐ HTC ☐ SAL ■ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Italianate two-part commercial block building with cast iron and pressed tin front elevation. Prominent cornice with brackets and triangular pediment features 1900 date.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

■ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
■ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	■ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
■ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
■ Solid stone
☐ Other _____

Wall Facade:

7 Number of bays
☐ Stucco
■ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
■ Metal
☐ Siding, type _____
☐ Fieldstone veneer
■ Awning(s)
■ Other cast iron, pressed tin

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

■ Fixed
■ Wood sash
■ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
■ Other 1st flr fixed, 2nd dblhng

Doors:

☐ Single-door primary entrance
■ Double-door primary entrance
■ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
■ Rectangular
☐ Other _____

Foundation:

■ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 14847

3. Integrity

■ Location ■ Design ■ Materials ■ Workmanship ■ Setting ■ Feeling ■ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1900 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Front facade fabricated by Mesker Brothers of St. Louis, Missouri

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 10, LOT 11-12

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-89

1. Identification

County Williamson City Round Rock

Current name Friar Tuck's Pantry Historic name Economy Drugstore

Address 204 East Main Street

Owner/address MARJORIE B. QUICK, TRUSTEE/E&M QUICK LIVING TRUST, c/o DON QUICK, 1000 N. IH-35, STE. A, ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story commercial block building with 19-foot ceiling, cast-iron and pressed-tin facade. Office space in rear mezzanine. Parapet topped with pressed-metal sign "Economy Drug Store". Inset double door flanked by display windows; transoms above wind./door

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☒ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☒ Awning(s)
☒ Other corr. metal awning

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other display windows

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☐ With sidelights
☒ Other inset doorway

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Stories: 1 **Basement:** ☐ None ☒ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1920 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 21, LOT 7-8 PTS

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-90

1. Identification

County Williamson City Round Rock

Current name Greater Round Rock Community Foundation Historic name Dr. Gregg's Office

Address 206 East Main Street

Owner/address TRJ NELSON PARTNERSHIP, 3404 GLENVIEW AVE., AUSTIN,TX 78703-1449

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story brick building with notched parapet. Inset brick panel above transom/cloth awning. Centered single-entry door flanked by one 1-over-1 window on each side. Appears to have had veneer below windows, since removed. Single window on east wall.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☐ Frame
- ☐ Adobe
- ☒ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☒ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☒ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 704

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☒ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☒ Other Charitable organization

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 21, LOT PT 6-7

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-91

1. Identification

County Williamson City Round Rock

Current name Palm House Museum/Round Rock Chamber of Commerce Historic name Andrew J. Palm House

Address 212 East Main Street

Owner/address ROUND ROCK CHAMBER OF COMMERCE, 212 E MAIN ST., ROUND ROCK,TX 78664-5245

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☒ NR District (Is property contributing? ☒ Yes ☐ No) ☒ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story cottage with massive two-story rear addition (ground slopes away to the rear of property). Center door with two 6-over-6 windows on either side. Working shutters on front windows. Roof extends over porch; plain wooden posts, wood deck.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Wood picket fence surrounds front yard. Stone sidewalk. Shrubs.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 1 Specify number(s)
- ☐ Interior
- ☒ Exterior
- ☐ Brick
- ☒ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other working shutters

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☒ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☒ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☒ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ■ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1873 ■ Actual ☐ Estimated Source: "Historical Round Rock," page 263

■ Additions/modifications, specify dates: 1986 - two-story, 5402 sq ft addition to rear of original building

■ Relocated, specify former location and reason: Relocated from Palm Valley to this location in 1976

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 21, LOT 3-5, 2(10'OF) & 6(15'OF)

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-92

1. Identification

County Williamson City Round Rock

Current name Round Rock Public Library Historic name Round Rock City Hall/Fire Station (prev. 214 E. Main)

Address 216 East Main Street

Owner/address CITY OF ROUND ROCK, 221 E MAIN ST., ROUND ROCK,TX 78665

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Irregular/asymmetrical stone block/veneer building. Front facade in two sections: original building & addition.

Massive metal arched cover over entrance. Large segmental-arch windows on addition quote smaller versions on original building. Rear 2nd addition.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

?___ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0___Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☒ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ■ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ■ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1936 ■ Actual ☐ Estimated Source: "Historical Round Rock," p. 340

■ Additions/modifications, specify dates: Library constructed 1999; renovation 2008

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 21, LOT 1-5, 6(15'OF) & 12-15

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-93

1. Identification

County Williamson City Round Rock

Current name City of Round Rock City Hall Historic name _____

Address 221 East Main Street

Owner/address CITY OF ROUND ROCK, 221 E. MAIN ST., ROUND ROCK,TX 78665

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Rectangular building with clipped corners on north side. Fieldstone veneer within cast stone wall and window frames. Main entrance on west facade. Connector to 231 East Main at second floor level.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other courtyard/hardscape with mature trees

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☒ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☒ Other two clipped corners

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 3 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: ca. 1986 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 10, LOT 1-5 & 13-16 & VAC ALLEY

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-94

1. Identification

County Williamson City Round Rock

Current name City of Round Rock Business Center Historic name _____

Address 231 East Main Street

Owner/address CITY OF ROUND ROCK, 221 E. MAIN ST., ROUND ROCK,TX 78665

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Two-story commercial office building. Fieldstone veneer within cast-stone frames around walls, windows. Half-rounds in cast stone, divided into wedges, above 2nd floor windows. North side upper windows bump out over window walls. NW clipped-corner entry.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☒ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☒ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: Lindel Fair Construction

Construction date: 1986 ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 10, LOT 17-19

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-95

1. Identification

County Williamson City Round Rock

Current name P&A Snack Center Historic name _____

Address 300 East Main Street

Owner/address PHUC M. NGUYEN & AN VINH VU, 1416 WEATHERFORD DR., AUSTIN,TX 78753

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Standalone one-part commercial building. Fieldstone veneer. Faux mansard "roof" above awning over front facade. Built as two storefronts, each with door + tri-part display window. Stone pillar at SE corner with sign. Carport attached on east side.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☒ Other faux mansard front

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☒ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other 2ndry single door

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1260

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1960 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 20, LOT 8-9 S PTS OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-96

1. Identification

County Williamson City Round Rock

Current name Goergen Properties -- Professional Floors Historic name _____

Address 302 East Main Street

Owner/address BARBARA GOERGEN, 2200 GREAT OAKS DR., ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Heavily modified four-square house. Bisected front facade with single 1-over-1 window on left side; door plus 6x5 lite rect. bay window on right side. Decorative pilasters flank large window. Front yard converted to concrete parking and handicapped ramp.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☒ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1552

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: 128 sq. ft. addition 2002. Front facade is heavily altered; may have been Greek Revival?

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: 1992 photo better shows band of "entablature" wood trim and pilasters.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ■ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 20, LOT 6 & 7

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-97

1. Identification

County Williamson City Round Rock

Current name Pena Swayze & Co. CPA Historic name

Address 303 East Main Street

Owner/address ROUND ROCK MAIN STREET VENTURE LLC, P.O. BOX 250, ROUND ROCK,TX 78680-0250

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Craftsman bungalow with rectangular addition built across (and 2x wider than) entire front facade. Addition attempts to quote Craftsman features of orig. bldg with oversized attic gable vents, center front entry below gabled porch roof, size/spacing of windows.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☒ Other shed roof front addition

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type Hardie
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other vinyl

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☒ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☒ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 4135

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

D-97

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ■ Estimated Source: 1992 survey photos

☐ Additions/modifications, specify dates: 1997 addition

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Previous site of J. A. Stamline house until 1915

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect ☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 11, LOT 11-13

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-98

1. Identification

County Williamson City Round Rock

Current name Design Systems Group Historic name

Address 304 East Main Street

Owner/address RITCHIE & DOWDEN LP, 304 E. MAIN ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Craftsman bungalow with 2-story + 1-story addition built on front. Remnants of cross-gabled roof visible at rear

Now gabled 2-story asymmetrical building with no aesthetic value. Brick chimey extends through 1-story roof. Another 1-story flat-roof addition to east.

Outbuildings (Specify number and type):

Garage 1 det. Barn _____ Shed _____ Other Garage extends across rear of property.

☐ Archeological evidence of outbuildings, specify

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Most of lot is paved with concrete

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☒ Awning(s)
☐ Other _____

Chimneys:

1 Specify number(s)
☒ Interior
☐ Exterior
☒ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☒ Other solar screens

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☒ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 + 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2090

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1925 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: 2 story + 1 story addition to front; flat-roofed 1-story addition to east side.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 20, LOT 3/PT, 4 & 5

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-99

1. Identification

County Williamson City Round Rock

Current name Quick Office Centre Historic name

Address 306 East Main Street

Owner/address MARJORIE B. QUICK, TRUSTEE/E&M QUICK LIVING TRUST, c/o DON QUICK, 1000 N. IH-35, STE. A, ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story L-plan office building with stone columns supporting roof over concrete-deck porch. Shallow gabled dormers with triangular windows; 4 face East, 2 face South. Two offices face East, two face South; with single-entry doors and double-hung windows.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☒ Dormers:
  - ☒ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 8 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type Hardie
- ☒ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other vinyl

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☒ Other four of these

Plan:
- ☒ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☒ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☒ Other stone-veneer columns
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3480

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 2006 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): 306 EAST MAIN ST SUB, BLOCK 20, Lot 1A

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-100

1. Identification

County Williamson City Round Rock

Current name Edward Jones Investments Historic name _____

Address 307 East Main Street

Owner/address ROUND ROCK MAIN STREET VENTURE LLC, P.O. BOX 250, ROUND ROCK,TX 78680-0250

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Craftsman with shed-roof wraparound porch that extends into front gable. Bracketed porch and main rooflines. Attic vents. Center door flanked by pair of double-hung windows on each side. Concrete porch deck, brick piers under wood columns.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☒ Metal standing seam/porch
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other 3 vertical lites-over-1-sq

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☒ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☒ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other metal railing

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1268

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

D-100

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1925 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 11, LOT 14-16, 20'ALLEY PT & N 20'OF 4 PT,5-6,7 PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-101

1. Identification

County Williamson City Round Rock

Current name Attorney Historic name

Address 309 East Main Street

Owner/address STEPHAN L. SHEETS, 309 E. MAIN ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Irregular Folk National building; originally L-plan with east addition. Out-of-scale, commercial-style standing seam metal, hip-on-gableroof. Front porch with classical columns. Decorative front door with sidelights.

Outbuildings (Specify number and type):

Garage 1 Barn _____ Shed _____ Other 3-car detached garage/carriage house with carport and large parking lot behind house.

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Circular driveway in front of house

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☒ Other Hip-on-gable

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal standing seam metal
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 1 Specify number(s)
- ☐ Interior
- ☒ Exterior
- ☒ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☒ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☒ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☒ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☒ Other hip-on-gable

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2994+1996

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☒ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1921 ☐ Actual ■ Estimated Source: Historic building placard

■ Additions/modifications, specify dates: 1996-97 addition to east wing

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 11, LOT 1-3, 4 (9' OF) & 17-19

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-102

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 400 East Main Street

Owner/address AVERY, JOHN S, Sr. (O065555) 2803 PECOS ST AUSTIN,TX 78703

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Minimal Tradiational house with unusual arched entryway with bracketed, hooded cover. Inset side porch, rear screened porch. Front porch deck with brick-capped stucco balustrade projects beyond roof. (Similar side porch.) 3-vertical-over-1-square-lite windows.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☒ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Min. Tradl.

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☒ Other hip on gable

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☒ Other stucco below watertable

Chimneys:

1 Specify number(s)
☐ Interior
☒ Exterior
☒ Brick
☐ Stone
☐ With corbelled caps
☒ Stuccoed
☒ Other through eave

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other storm windows

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☒ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other arched covered entry

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1704

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ■ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 19, LOT 5 W 35' OF & ALL 6,

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

■ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: Architecture

Period(s) of significance: 1930-1960

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-103

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 402 East Main Street

Owner/address SARAH N. ROBERTS, 402 E. MAIN ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Tudor Revival cottage with arched front entry under steep center gable. Prominent exterior chimney on front facade. Bracketed eaves. Second gabled section to rear extends wider than front section, with connector between.

Outbuildings (Specify number and type):

Garage 1 det. Barn _____ Shed _____ Other Appears to have original garage door; rear detached carport

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Screened porch with deck at rear of house

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☒ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

1 Specify number(s)
☐ Interior
☒ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☒ Stuccoed
☒ Other tapered with brick cap

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☒ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☒ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other enclosed on sides

Stories: 1 1/2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1280

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☒ Setting ☐ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OFROUND ROCK, BLOCK 19, LOT 4 & E 10 FT 5

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

■ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: Architecture

Period(s) of significance: 1930-1960

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-104

1. Identification

County Williamson City Round Rock

Current name Nelson-Crier House Historic name Woodbine Mansion

Address 405 East Main Street

Owner/address BILLIE JEAN GOODRICH, WM. CRIER & JACK CRIER/GOODRICH REV. TRUST, 405 E. MAIN ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ■ RTHL ☐ HTC ☐ SAL ■ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Neoclassical brick mansion with full-facade front porch, Ionic columns, balcony with balustrade, verandahs. Circular drive with porte cochere on west elevation.

Outbuildings (Specify number and type):

Garage 2cardet Barn 1 Shed 1 Other cottage at rear of property

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

■ Sidewalks ☐ Terracing ■ Drives ☐ Well/cistern ☐ Gardens ■ Other wooden picket fence and gates

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	■ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ■ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ■ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ■ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ■ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 4 Specify number(s)
- ■ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ■ Wood sash
- ■ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☐ Single-door primary entrance
- ■ Double-door primary entrance
- ☐ With transom
- ■ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ■ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ■ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ■ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ■ Spindlework
- ☐ Jig-sawn trim
- ■ Other flat roof with balcony

Stories: 2 1/2 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 5710

3. Integrity

■ Location ■ Design ■ Materials ■ Workmanship ■ Setting ■ Feeling ■ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: Page Brothers Builder: A. J. Nelson family

Construction date: 1900 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: 1931 changed to Greek Revival/Neoclassical style; 1966 four rooms added to rear of house

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: 1931 renovation by architect Wilson McClure, AIA, Dallas

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 12, LOT 1-12

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

■ B. Associated with the lives of persons significant in our past;

■ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: Architecture, association with Nelson family

Period(s) of significance: 1900-1960

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-105

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 406 East Main Street

Owner/address JEAN W. & ROGER L. COLEMAN, 406 E. MAIN ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Gable-roof house with peaks in roof above windows on first and second floors. Spindlework in 1st floor peak. Lower front facade has brick veneer and vinyl siding; front inset porch and second story in vinyl siding.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other wrought iron decorative fence with brick posts in front, side yards

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☒ Other peaks over windows

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type vinyl
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☒ Other brick veneer

Chimneys:
- 1 Specify number(s)
- ☒ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☒ Other vinyl siding

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☒ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☒ Inset
- ☒ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☒ Jig-sawn trim
- ☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1964

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1983 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 19, LOT 3, ACRES .13

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ■ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-106

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 408 East Main Street

Owner/address VERONICA ASENCIO, 47 FAIRVIEW, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story gable-front-and-wing brick veneer house with vinyl siding in front gable. Bay window in gable front. Inset porch w/ roof that extends around second bay window. Chimney. Round window above rear addition.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type vinyl
☐ Fieldstone veneer
☐ Awning(s)
☒ Other brick veneer

Chimneys:

1 Specify number(s)
☒ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☒ With sidelights
☒ Other one sidelight

Plan:

☒ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other concrete deck

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1472

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1983 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: Appears to have rear addition, date unknown

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 19, LOT 2, ACRES .13

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ■ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-107

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 410 East Main Street

Owner/address DAVID W. LEPPIN, 508 E. MAIN ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story brick veneer gable-front-and-wing house with round vent and bay window in front gable. Roof extends over porch, across entire wing. Spindlework and turned wooden posts. Roof has two small, front-facing gable dormers with windows.

Outbuildings (Specify number and type):

Garage 1 det. Barn _____ Shed _____ Other One-car garage with integrated carport under half of gabled roof.

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☒ Dormers:
- ☒ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type vinyl
☐ Fieldstone veneer
☐ Awning(s)
☒ Other brick veneer

Chimneys:

1 Specify number(s)
☒ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☒ Other Hardie siding?

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☒ With sidelights
☒ Other single sidelight

Plan:

☒ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☒ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1524

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1983 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 19, LOT 1

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ■ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-108

1. Identification

County Williamson City Round Rock

Current name Martin A. Harris, Attorney Historic name was 100 South Mays Street

Address 101 West Main Street

Owner/address MARTIN A. HARRY, 5804 MAGEE BEND, AUSTIN,TX 78749

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Former gas station converted to offices. Canopy remains; but original notched parapet has been removed and canopy integrated with roof of building. Area beneath canopy enclosed with 4' metal picket fence. Building is covered in stucco, front windows replaced.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other About 4 street parking spaces

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Handicapped access on N side; door is at ground level, no ramp.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Gas Station

Structural Details:

Roof Type:
- ☐ Gable
- ☒ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☒ hipped
  - ☐ shed
- ☒ Other 2 dormers

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- ____ Number of bays
- ☒ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☒ Other Orig. single door on E si

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☒ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☒ Other Canopy
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1250

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☒ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1980 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: Building covered with stucco. Parapet removed. Canopy roof integrated with roof of rear building.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Gazebo next to building represents the old town well.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ■ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 8, LOT 17 NE/PT & 18-19 N/PT & 40.55 SFT OF MAIN ST

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-109

1. Identification

County Williamson City Round Rock

Current name Soleil Floors Historic name Rubio's Grocery

Address 107 West Main Street

Owner/address MARIO RUBIO, 10712 FM 1625, AUSTIN,TX 78747

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One of several one-part commercial block bldgs on this block. Original facade is intact with notched wooden parapet, shingled awning supported by simple bracketed posts, two single-entry doors in center flanked by three door-height windows on either side.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other 3 street parking spaces

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☒ Other slopes to rear of buildin

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☒ Other unknown

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type Vertical wood
☐ Fieldstone veneer
☒ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☒ Other 9 over 6 lights

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☒ Setting ☐ Feeling ☐ Association

4. Function

D-109

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Rubio's grocery moved from Rubio Street to this location in 1969.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): City of Round Rock, BLOCK 8, Lot 17/PT N

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-110

1. Identification

County Williamson City Round Rock

Current name Vacant Historic name

Address 109 West Main Street

Owner/address MACK & JANIE & LORENZO RUBIO & MANUELA G. RUBIO, 506 DOVE HAVEN, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial block building; wood frame with two large display windows and single entry door.

Horizontal siding. Shingled awning supported by bracketed wooden posts.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☒ Other unknown

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type Aluminum
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2150

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 8, LOT 15-16/N 1/2 OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-111

1. Identification

County Williamson City Round Rock

Current name Domino's Pizza Historic name _____

Address 111 West Main Street

Owner/address SAMACO LLC, 816 WINDSOR HILL DR, PFLUGERVILLE,TX 78660

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story with no parapet. Large illuminated sign tops facade above standing-seam metal awning. Awning supported by wooden posts. Front facade covered with stucco. Entry door with sidelight flanked by two display windows on each side.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other 3 street parking spaces in front of building

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☒ Other Flat without parapet

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☒ Other unknown

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☒ Other Concrete masonry units

Wall Facade:

3 Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☒ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☒ With sidelights
☒ Other sidelight to right of door

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2100

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 8, N 75 FT OF LOT 14

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-112

1. Identification

County Williamson City Round Rock

Current name El Matador Mexican Restaurant Historic name Round Rock Ice House and Bottling Works

Address 113 West Main Street

Owner/address JOSEPH FAMILY TRUST, c/o MARGARET E JOSEPH, 1902 OAK RIDGE DR., ROUND ROCK,TX 78681

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One story, cross-gabled roof on original bldg with front gable over main entry No supports below front gable.

Stucco facade w/ fixed windows. Addition to front west has flat roof w/ single door, sliding vinyl windows. Rear addition w/ vertical siding, shed roof.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other 10 spaces street parking.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☒ Other Addn flat roof; addn she

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type vertical rear addn
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☒ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 4492

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ■ Estimated Source: Historical Round Rock," pp. 310-315

■ Additions/modifications, specify dates: Additions to west and rear (south) sides of original building

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Replaced a smaller ice house on same lot built ca. 1925

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 8, LOT 11-13 N PTS OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ■ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-113

1. Identification

County Williamson City Round Rock

Current name Kanda Kropp State Farm Insurance Historic name

Address 200 West Main Street

Owner/address GEORGE MURRAY, 6401 WILLIAMS RIDGE WAY, AUSTIN,TX 78731-2708

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Building may be adapted auto repair garage extant on site in 1920s-30s. Front elevation features garage-sized window wall infill with gabled porch addition. Side porch to south and newer addition to rear (west). Drive-through window on north side.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ■ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	■ Other Folk Natl.

Structural Details:

Roof Type:
- ■ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ■ Other hipped roof west side

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ■ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ■ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 5 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ■ Siding, type vertical wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ■ Double hung
- ☐ Casement
- ■ Aluminum sash
- ☐ Decorative screenwork
- ■ Other mult 28-lite flr-to-ceiling

Doors:
- ■ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ■ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ■ Pier and beam
- ■ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ■ Gable roof
- ☐ Inset
- ■ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ■ Other gabled side porch

Stories: 1 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2472

3. Integrity

■ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1956 ☐ Actual ☒ Estimated Source: WCAD

☒ Additions/modifications, specify dates: Possible adapted auto garage. Served as residence in 1980s.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 24, LOT 1-5

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-114

1. Identification

County Williamson City Round Rock

Current name ONCOR Electric Delivery Historic name _____

Address 203 West Main Street (listed in WCAD as 207)

Owner/address ONCOR ELECTRIC DELIVERY COMPANY, P.O. BOX 219071, DALLAS,TX 75221-9071

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial building. Fieldstone veneer with gable roof, front and rear stepped parapets. Awning across entire front facade with standing seam metal, wood posts. Roof extends over window on east side, possible former drive-through.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other 27 parking spaces on site

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☒ Other front/rear parapets

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☒ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☒ Other 12-lite fixed on front

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3484

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1982 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 7, LOT 16-19

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-115

1. Identification

County Williamson City Round Rock

Current name Market Square Shops/Offices (various tenants) Historic name _____

Address 206 West Main Street

Owner/address MARION L. & TERRY A. COOK, JR. 9606 N. MOPAC STE. #125, AUSTIN,TX 78759

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Large commercial office/retail building with multiple spaces. Mostly fieldstone veneer with some rustic wood siding. Red cloth awnings over segmental-arched doorways and windows. Service entrances & HVAC units on south side.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other 25 parking spaces on site

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☒ Metal standing seam
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

6 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☒ Fieldstone veneer
☒ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 11282

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1983 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 24, LOT 8-11, PTS 6-7, PT 12, ACRES .541

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-116

1. Identification

County Williamson City Round Rock

Current name Texas Pioneer Farm Mutual Insurance Association Historic name

Address 209 West Main Street

Owner/address TEXAS PIONEER FARM MUTUAL (O084633) 209 W MAIN AVE ROUND ROCK,TX 78664-5827

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Cross-gabled ranch with stone veneer. Front gable extends over inset porch; vertical siding on pediment.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other 3 on-site parking spaces; slight concrete ramp to slab porch

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☒ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- ____ Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☒ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☒ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☒ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1554

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1965 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK , BLOCK 7, LOT 13 PT, 14 & 15

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-117

1. Identification

County Williamson City Round Rock

Current name Jane C. McKennon, Attorney at Law Historic name

Address 211 West Main Street

Owner/address JANICE CROSBY MCKENNON, 211 W. MAIN ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Bungalow covered in stucco; attic window/vent. Original brick piers and tapered box columns on porch have been replaced by wooden posts. Detached 2-car garage in rear converted to office space at least since 1990s.

Outbuildings (Specify number and type):

Garage 1 det. Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other commercial-scale sidewalk to west on Brown Street

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☒ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 2 Specify number(s)
- ☒ Interior
- ☒ Exterior
- ☐ Brick
- ☐ Stone
- ☒ With corbelled caps
- ☒ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☒ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☒ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☒ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1632

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1920 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: 256 sq ft addition 2005; porch altered between 1992 and 2010

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 7, LOT 11, 12 & 13 1/2 OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-118

1. Identification

County Williamson City Round Rock

Current name Round Rock Flowers Historic name _____

Address 212 West Main Street

Owner/address NAGLE HOLDINGS LP, 400 W. MAIN ST. STE 210, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Craftsman cross-gabled bungalow with partially enclosed front porch, bracketed gable eaves, shed-roofed addition to rear. One of the later and larger bungalows in Round Rock. 6' wooden privacy fence around back yard.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other 5 parking spaces on site (unpaved gravel)

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other Handicapped access on East side, wooden ramp and handrails

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 5 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☐ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☒ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☒ Inset	☐ Spindlework
☒ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☒ Other covered balusters
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1925

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

D-118

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ☒ Estimated Source: WCAD

☒ Additions/modifications, specify dates: Shed-roofed addition to rear, date unknown

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): NAGLE SUB, BLOCK A, Lot 1

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☒ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: 1930-1960

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☒ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☒ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-119

1. Identification

County Williamson City Round Rock

Current name Children's Guitar Studio Historic name Landrum-Ledbetter House

Address 302 West Main Street

Owner/address JOHN W. LEDBETTER SR, TRUSTEE OF THE JOHN W. LEDBETTER LIVING TRUST, 919 ANGELA DR, LEWISVILLE,TX 75067

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Greek Revival cottage with with two-story addition rear (north) addition. Original house is intact. Gabled pediment over front entry; door features transom and sidelights. Wide band of trim below cornice.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other Integrated carport/parking under part of 2-story addition

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☒ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

1 Specify number(s)
☐ Interior
☒ Exterior
☐ Brick
☒ Stone
☐ With corbelled caps
☐ Stuccoed
☒ Other covered in ivy

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other aluminum in addition

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☒ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☒ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☒ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☒ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☒ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 (2-st. addn.) **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2124

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☐ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1880 ☐ Actual ■ Estimated Source: Deeds

■ Additions/modifications, specify dates: 380 sq ft addition above carport to rear, date unknown

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ■ Other structural instability * **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 25, LOT 1-2

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

■ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: One of the oldest extant houses in the City and an excellent example of Greek Revival cottage building.

Period(s) of significance: 1880-1960

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-120

1. Identification

County Williamson City Round Rock

Current name Leffingwell & Associations PC -- John R. C. Munn, CPA PLLC Historic name _____

Address 304 West Main Street

Owner/address JOHN E. & LAURIE LEVEE LIVING TRUST, 310 W. MAIN ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Craftsman bungalow wiht scalloped shingles in front gable. Entire front yard landscaped with boxwoods. Modern wood picket fence around back yard. Handicapped ramp and office signage in front of most of front porch.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other Front yard almost entirely converted to parking

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☒ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other Scallop-shingled gable

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1196

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☐ Setting ☒ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 25, LOT 3 & 4

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-121

1. Identification

County Williamson City Round Rock

Current name Bella Capelli Salon Historic name _____

Address 306 West Main Street

Owner/address KELLY JEAN KRESSER & STEPHEN JAMES KRESSER, 275 SHELL STONE TRL., GEORGETOWN,TX 78628

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Cottage with hipped roof, center front gable dormer, probable finished attic. Inset front porch with turned posts and spindlework. Front yard has been largely paved for parking.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Front yard has been largely paved for parking.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☐ Gable
- ☒ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☒ Dormers:
  - ☒ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☒ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☒ Hipped roof
- ☐ Gable roof
- ☒ Inset
- ☒ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☒ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 1/2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1654

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1930 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 25, LOT 5 & 6 E 1/2 OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

■ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: Architecture

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ■ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-122

1. Identification

County Williamson City Round Rock

Current name Vacant Lot Historic name

Address 307 West Main Street

Owner/address DAIN JAY JOHNSON, 307 W. MAIN AVE., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Orange and buff fieldstone veneer ranch-style house with casement windows and attached garage with original garage door. NOTE: This building was moved after survey fieldwork was completed, in order to make way for the City Transit Center.

Outbuildings (Specify number and type):

Garage 1 att. Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Min. Tradl.

Structural Details:

Roof Type:
- ☐ Gable
- ☒ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☒ Other irregular roof lines

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☒ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☒ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☒ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☒ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☒ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☒ Other stone veneer columns

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1224

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ■ Other Demolished

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1945 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 6, LOT 15-17 & 5PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-123

1. Identification

County Williamson City Round Rock

Current name Principal Financial Group Historic name _____

Address 308 West Main Street

Owner/address JAMES E. LEDBETTER, 919 ANGELA DR, LEWISVILLE,TX 75067

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Front-gabled Folk National house with two-room front facade; gabled cover over front stoop is supported by brackets rather than posts. Appears to retain original materials. House has been encroached upon by large commercial building on property to west.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Sidewalk from front door to curb; no sidewalk parallel to street

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☒ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☒ Other concrete stoop

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 768

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

D-123

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1915 ☐ Actual ☒ Estimated Source: 1916 Sanborn Map

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 25, LOT 7, 6(W/PT)

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☒ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: Architecture

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☒ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-124

1. Identification

County Williamson City Round Rock

Current name Harrell Henna House Professional Offices Historic name Harrell-Henna House

Address 309 West Main Street

Owner/address ROUND ROCK DEVELOPMENT LLC, 400 W. MAIN ST. STE. 210, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Appears to be a 2-story addition to 1-story cottage, joined with connector. Brick, Hardie siding, with fieldstone veneer over lowest 3' of 1st floor facade. Faux pergola on north side. Gabled dormers on 2-story section. Covered entry on northeast corner.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☒ Dormers:
- ☒ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

5 Number of bays
☐ Stucco
☐ Stone
☒ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type Hardie
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☒ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☒ Gable roof
☐ Inset
☒ Wood posts
☒ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 and 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 7036

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: ca. 1900 ☐ Actual ■ Estimated Source: "Historical Round Rock", p. 181

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Converted to Condra Funeral Home in late 1940s

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 6, LOT 11-14/PTS

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-125

1. Identification

County Williamson City Round Rock

Current name Advanced Wealth Strategies Group Historic name _____

Address 310 West Main Street

Owner/address LEVEE UNLIMITED INC., 310 W. MAIN AVE., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Two-story commercial office building. Vaulted and hipped roofs; bracketed eaves; Craftsman-style windows; some arched windows and doors. Stucco with fieldstone veneer on parts of first-floor facade. Entrances on Main and Brown (multiple offices).

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☒ Other barrel vaulted

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☒ Metal standing seam
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other decorative muntins

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☒ With transom
☒ With sidelights
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☒ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3902

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 2008 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ■ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 25, LOT 8 & 9

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-126

1. Identification

County Williamson City Round Rock

Current name Nagle Building Historic name Weber-McNeese House

Address 400 West Main Street

Owner/address NAGLE HOLDINGS LP, 400 W. MAIN ST. STE. 210, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Original building on corner is surrounded by L-shaped contemporary building. Original building damaged in fire; might have had second floor but repaired as one-story. Large dormers added later. Bay window and wraparound porch.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other additional building wraps around on north and west sides to form office complex

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Yard mostly converted to on-street parking on both sides of corner

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other ????

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☒ Dormers:
  ☒ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☒ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☒ Other wood over bay window

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other fixed in dormers

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☒ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☒ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☒ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☒ Hipped roof
☐ Gable roof
☒ Inset
☒ Wood posts
☐ Brick piers
☒ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 1/2 (?) **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☒ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1910-1915 ☐ Actual ☒ Estimated Source: First appears on 1916 Sanborn Map

☒ Additions/modifications, specify dates: 2171 sq ft addition, 1975; upper floor destroyed by fire (date unknown); new dormers added in 2000s

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Had 1-car garage as well as servants' quarters to west of house. Garage faced Main Ave

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 26, LOT 1 & 2-4(PTS), 5

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☒ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-127

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 403 West Main Street

Owner/address KYLE R. HUMPHRIES & DEBRA R. SPELLINGS, 405 W MAIN AVE, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Gable-and-wing Folk National cottage. Porch has been altered; hipped roof have been replaced with shed roof and turned posts have been replaced with 4x4s (prob. treated lumber). Circular attic vent in front gable. Substantial loss of yard to street, parking.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other handicapped ramp on south side with wooden ramp, handrails

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type cement board
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☐ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☒ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☒ Perimeter wall
- ☐ Other _____

Porches:
- ☒ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☒ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☒ Other rear porch

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 826

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1910 ☐ Actual ■ Estimated Source: WCAD, also first appears on 1916 Sanborn Map

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK (REPLAT OF LT 4-6, BLK 5), BLOCK 5, LOT 1A, ACRES .1921

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain Porch has been altered but changes are reversible.

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-128

1. Identification

County Williamson City Round Rock

Current name Spelling & Humphries LLP Historic name

Address 405 West Main Street

Owner/address DEBRA R. SPELLINGS & KYLE R. HUMPHRIES, 209 WHITETAIL LN., HUTTO,TX 78634

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Minimal traditional house with random fieldstone veneer, standing seam metal roof. Small gable front ell plus addition to east side.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Wrought iron fence around backyard; trellis across front facade

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Min. Tradl.

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal standing seam
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☒ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☒ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1644

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ■ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK (REPLAT OF LT 4-6, BLK 5), BLOCK 5, LOT 2A

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-129

1. Identification

County Williamson City Round Rock

Current name _____ Historic name _____

Address 407 West Main Street

Owner/address DORA H. ROBERTSON, 348 LUNDY RD., JUNCTION,TX 76849-6048

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Irregular plan house with ashlar fieldstone veneer, hipped roof with gable-on-hip at peak. Inset porch.

Outbuildings (Specify number and type):

Garage 1 car Barn _____ Shed _____ Other Garage with flat roof

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ■ Other wooden handicapped ramp with handrail in poor condition

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	■ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
■ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
■ Other gable-on-hip at peak

Roof Materials:

☐ Wood shingles
☐ Tile
■ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

■ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
■ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
■ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

■ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
■ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

■ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
■ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
■ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
■ Other dec. wood trim above

Stories: 1 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2415

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ☐ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 5, LOT 7, PT 8, PTS 2-3 & AW0298 HARRIS W. SUR.

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-130

1. Identification

County Williamson City Round Rock

Current name Texas Academy of General Dentistry (TAGD) Historic name

Address 409 West Main Street

Owner/address TEXAS ACADEMY OF GENERAL DENTISTRY (O487240) 409 W MAIN ST ROUND ROCK,TX 78664-5831

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Contemporary 1 1/2 story house with oversized gable roof. Fieldstone veneer over most of facade with wood siding between windows on first floor, around garage door on west elevation, and within gable.

Outbuildings (Specify number and type):

Garage 1 att. Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other 6' wood privacy fence around back yard

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

1 Specify number(s)
☐ Interior
☒ Exterior
☐ Brick
☒ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☒ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1-1/2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2226

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1970 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 5, LOT 8 W/PT, AW0298 HARRIS, W. SUR.,

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-131

1. Identification

County Williamson City Round Rock

Current name Garcia's Mexican Restaurant Historic name _____

Address 410 West Main Street

Owner/address UT VAN PHAM, 1130 FOREST BLUFF TRL., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Residence converted to restaurant. Vent system East roof, exterior light, 6-ft privacy fence around backyard.

Addition to original building on East side. Signage on building and in yard near corner of property. No landscaping.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other Street parking - 8 spaces

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ■ Other hanicapped accessible ramp to front porch on south side

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	■ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ■ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ■ Other shed roof on addition to

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ■ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ■ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- ____ Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ■ Siding, type Wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ■ Fixed
- ■ Wood sash
- ■ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ■ Other solar screens

Doors:
- ■ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ■ Other single-door rear W entra

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ■ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
■ Gable roof	☐ Fabricated metal
■ Inset	☐ Spindlework
■ Wood posts	☐ Jig-sawn trim
☐ Brick piers	■ Other gabled cover over rear e
☐ Box columns	

Stories: 1 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1162

3. Integrity

■ Location ■ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ■ Estimated Source: WCAD

■ Additions/modifications, specify dates: Large shed-roof addition on East side of building

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 26, LOT 6-9 PTS OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ■ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-132

1. Identification

County Williamson City Round Rock

Current name McVey Insurance - The Johnson Building - Life Force Fitness Historic name Filing Station

Address 102 North Mays Street

Owner/address JOHNSON HOLDINGS LLP, 102 N. MAYS ST., ROUND ROCK,TX 78664-5132

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Former gas station retains canopy; owner has added Texaco signage and fuel pumps. Original entrance and d

Large two-story addition to rear of original one-story building. Both sections are covered with stucco.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other On-site parking spaces under canopy and next to building.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Gas station

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☒ Other Unknown

Construction:
- ☐ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☒ Other possibly CMU

Wall Facade:
- ____ Number of bays
- ☒ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other vinyl

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☒ With transom
- ☐ With sidelights
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☒ Other canopy with lolly column

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☒ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 5294

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1935 ☐ Actual ☒ Estimated Source: 1937 Sanborn Fire Insurance Map

☒ Additions/modifications, specify dates: Two-story addition, possibly in 1996

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): JOHNSON'S ADDITION, LOT 1

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☒ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: 1935-1970

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☒ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☒ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-133

1. Identification

County Williamson City Round Rock

Current name TNT Financial Historic name Round Rock telephone exchange/switchboard

Address 106 North Mays Street

Owner/address BEVERLY BAKIR, PO BOX 882. ROUND ROCK,TX 78680-0882

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Gable front-and-wing Folk National house with hipped roof on wing; eaves continue across gable front, to create the illusion of a pediment. Hipped roof over front porch, shed roof over side porch. Vent in front gable. Wooden porch decks.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Folk Natl.

Structural Details:

Roof Type:
- ☒ Gable
- ☒ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☒ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☒ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☒ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☒ Other side shed roof
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1032

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☒ Setting ☒ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1905 ☐ Actual ■ Estimated Source: First appears on 1909 Sanborn map

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 23, LOT 13, 14(N/PT)

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-134

1. Identification

County Williamson City Round Rock

Current name Kawaii Shaved Ice and The Water Jug Historic name _____

Address 113 North Mays Street

Owner/address WATER JUG INC., 113 N. MAYS ST., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description 1-1/2 or 2-story building in 2 sections, each with hipped roof. Larger section to south houses "Water Jug"; smaller to north houses "Kawaii Ice." Stucco. Wide hipped porch roofs with round posts on square bases.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other large parking lot

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Palm trees

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☒ Other textured CMU?

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☒ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☒ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☒ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1+ **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1704

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 2003 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 22, LOT 10 & 11

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-135

1. Identification

County Williamson City Round Rock

Current name Huebinger Studios Photography Historic name

Address 205 North Mays Street

Owner/address STEPHANIE A. HUEBINGER, 205 N. MAYS, ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Rect. building with standing seam metal mansard roof over inset center of front facade, covering entry door, roll-up garage door, and three windows. Fieldstone veneer all but center section which is stucco. Glass block around single entry door.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other parking lot

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☒ Other faux mansard front

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal standing seam metal
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 5 Number of bays
- ☒ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☒ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other glass block

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☒ Other glass block surround

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2620

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1979 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 35, LOT 4 & 5

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-136

1. Identification

County Williamson City Round Rock

Current name Studio 105 Hair Salon Historic name

Address 105 South Mays Street

Owner/address TIEN V. NGUYEN & THI P. MAI, 1009 GAZANIA DR., PFLUGERVILLE,TX 78660

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-part commercial brick building. Two single-entry doors; left one with sidelights, both with cloth awnings. Display window in center of facade. Contrasting trim across top of facade (no parapet).

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☒ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☒ Awning(s)
☒ Other brick veneer

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☒ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1350

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 11 S 45 FT OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-137

1. Identification

County Williamson City Round Rock

Current name Action Sporting Goods Historic name S & S Grill

Address 106 South Mays Street

Owner/address KEATON & COMPANY LTD., 106 S. MAYS ST. STE. #300, ROUND ROCK,TX 78664-5852

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Two-story public house/restaurant now converted to retail. Covered in patterened stucco. Original symmetrical storefront has been expanded to north with 2nd storefront. Awnings over both storefront doorways. One-story entry on south elevation.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☒ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☒ Other fixed 1st, dblhng 2nd fl.

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other two of these

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 4508

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1936 ☒ Actual ☐ Estimated Source: Bob Brinkman files/book

☒ Additions/modifications, specify dates: 2nd entry added on Left, date unknown; expanded to north with 2nd storefront after 1992

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Building occupied by a series of restaurants 1936-1960s

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☒ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 8, LOT 16-19 S/PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-138

1. Identification

County Williamson City Round Rock

Current name Tischler and Kocurek Engineers Historic name Old Post Office/Masonic Lodge

Address 107 South Mays Street

Owner/address TISCHLER-KOCUREK c/o LIAL TISCHLER, 107 S MAYS ST, ROUND ROCK,TX 78664-5833

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ■ NR District (Is property contributing? ■ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ■ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Two-story solid limestone; brick corbell and accents; 4 single-entry doors at street level with half-round arched transoms. Building is about two rooms deep. Six-over-six wood sash windows on 2nd floor have cut stone sills with segmentally arched hoods above.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

■ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
■ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
■ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
■ Other unknown

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
■ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☐ Stucco
■ Stone
■ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
■ Wood sash
■ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

■ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
■ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
■ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2700

3. Integrity

■ Location ■ Design ■ Materials ■ Workmanship ■ Setting ■ Feeling ■ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☒ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☒ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1878 ☒ Actual ☐ Estimated Source: 1992 survey; date on building

☒ Additions/modifications, specify dates: Originally had large shed-roof awning with hitching post rails across front facade.

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Post office located here from 1878-1959; Masonic Lodge owned building from 1884-1984

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☒ No ☐ Not known **Possible threat(s):** ☒ None ☐ Damage (i.e. natural disaster) ☐ Neglect ☐ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 9, LOT 8-10

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☒ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☒ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☒ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☒ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-139

1. Identification

County Williamson City Round Rock

Current name Madsen Tire and Auto Historic name

Address 108 South Mays Street (listed in WCAD as 110)

Owner/address RONALD & JANETTE MADSEN, 1455 N. CR 122, ROUND ROCK,TX 78665

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Auto repair garage with multiple bays plus curved office area. Believed to be former Louis Henna dealership.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other parking lot

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other automotive

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- many Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☒ Metal
- ☒ Siding, type standing seam
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☒ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 3906 + 3696 servic

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☒ Setting ☐ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 8, LOT 1-4 & PT 5

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-140

1. Identification

County Williamson City Round Rock

Current name Lee's Body Shop Historic name _____

Address 110 South McNeil Road / 204 S. Mays Street

Owner/address LEES BODY SHOP C/O LEE GAYDOS, 110 MCNEIL AVE., ROUND ROCK,TX 78664-5836

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Automotive garage in two buildings, multiple bays.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other 6 stall x 2 deep pole barn with metal standing seam roof & siding

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other autmotive

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal standing seam
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3+4 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☒ Metal
- ☒ Siding, type plywood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2500

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☒ Association

4. Function

D-140

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1955 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 1, LOT 3-10 E 1/2 OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-141

1. Identification

County Williamson City Round Rock

Current name Peña House Historic name Peña House

Address 210 McNeil/Florence Street

Owner/address LEE R. PENA, JR., 110 FLORENCE ST, ROUND ROCK,TX 78664-5816

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Folk Victorian cottage with large rear addition. Brick or brick veneer surrounds foundation; board and batten sid brackets, and balusters suspended as friezes on front and rear porches. Standing seam metal roof. Center entry on both front and rear porches.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 rear Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☒ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal galv standing seam
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 3 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood board & bat
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☐ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other Vinyl

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☒ Other Single door rear entranc

Plan:
- ☒ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☒ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☒ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☒ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☒ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 980

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1905 ☐ Actual ■ Estimated Source: appears first on 1909 Sanborn Map

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Property in Peña family from 1925 to present

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 1, LOT 1 & 2 E PTS OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain Currently designated as a local landmark

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-142

1. Identification

County Williamson City Round Rock

Current name Life Force Fitness (Building For Sale) Historic name _____

Address 34 Round Rock Avenue

Owner/address JJOHNSON HOLDINGS LLP, 102 N. MAYS ST., ROUND ROCK,TX 78664-5132

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Large stucco box; any previously visible architectural details covered by stucco. Mix of double-hung, fixed, and display windows. Entry faces Round Rock Avenue but building is attached to 102 North Mays.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☒ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☒ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other display

Doors:

☐ Single-door primary entrance
☒ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☒ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1996 ■ Actual ☐ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): JOHNSON'S ADDITION, LOT 1

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-143

1. Identification

County Williamson City Round Rock

Current name Old Watertower Historic name _____

Address No Number, Round Rock Avenue (between 210 and 34)

Owner/address City of Round Rock, 221 East Main Street, Round Rock, TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ■ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Steel watertower on four steel braced legs. Tank constructed of riveted steel plates, with conical roof capped by a beacon finial. Main vertical structural beams have horizontal steel struts and diagonal support rods. Maintenance catwalk around tank base.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	■ Other watertower

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

■ Location ■ Design ■ Materials ☐ Workmanship ■ Setting ■ Feeling ■ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ■ Other Infrastructure/Utilities

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ■ Other Infrastructure/Utilities

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1938 ■ Actual ☐ Estimated Source: "Round Rock" Images of America book by Bob Brinkman

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 23, LOT 4 PT, 10 PT & 11 PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-144

1. Identification

County Williamson City Round Rock

Current name David W. Conrad, CPA Historic name _____

Address 209 Round Rock Avenue

Owner/address Pilot Peak Investments LLC, 209 Round Rock Avenue, Round Rock, TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Small four-square building. Hipped roof extends over inset entrance in NE corner, corner supported by stone column. Single door + window at entry surrounded by Hardie or wood siding. Fieldstone veneer with 2 double-hung windows in NW elevation.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other Four parking spaces on site

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type Hardie or wood
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other w/ single window

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☒ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other stone veneer column

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1993 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☐ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☒ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK (REPLAT LTS 16-19, BLK 24), BLOCK 24, LOT 17A

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-145

1. Identification

County Williamson City Round Rock

Current name Neighborhood Conference Committee Historic name previously Snapdragon Flowers 'N' Such (florist)

Address 210 Round Rock Avenue

Owner/address City of Round Rock, 221 East Main Street, Round Rock, TX, 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Heavily modified Queen Anne cottage. Reversible changes include unsympathetic bay window & greenhouse addition on west elevation plus addition to rear/east. Porch has fab. metal supports but retains suspended frieze. Jigsawn trim in front gable remains.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other Most of lawn has been paved for parking

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☒ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 2 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☒ Other also vinyl

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☐ Rectangular
- ☐ Other _____

Foundation:
- ☐ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☒ Fabricated metal
☒ Inset	☒ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☒ Other addl shedroof porch
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☒ Location ☒ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1900 ☐ Actual ☒ Estimated Source: Surveyor

☐ Additions/modifications, specify dates: _____

☒ Relocated, specify former location and reason: Was likely moved to this location; reads as 1890-1910 but not on Sanborn maps thru 1937.

Other associated contexts and information of interest: Entire block was originally a cotton yard.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☒ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): City Of Round Rock, BLOCK 23, Lot 8 & 9

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☒ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-146

1. Identification

County Williamson City Round Rock

Current name Alan McGraw, Attorney at Law/ Betsy Lambeth, Atty. at Law Historic name _____

Address 211 Round Rock Avenue

Owner/address Alan M. & Kathryn L McGraw, 2708 Wolkin Cove, Round Rock,TX 78681-2238

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story Minimal Traditional L-plan house with fieldstone veneer, hipped roof. Inset front porch faces RR Ave. Front porch across center of facade. Attached one-car garage has been converted with pair of windows set into garage door.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other Driveway off Brown Street to rear of house.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☒ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☒ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☒ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK (REPLAT LTS 16-19, BLK 24), BLOCK 24, LOT 16A

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-147

1. Identification

County Williamson City Round Rock

Current name Off The Top Hair Salon Historic name _____

Address 212 Round Rock Avenue

Owner/address GEORGETOWN TITLE CO., P.O. BOX 689, GEORGETOWN,TX 78627-0689

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☒ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Small square building with fieldstone veneer, large display windows, hipped mansard roof with hipped eaves over all four sides, supported at corners by posts. Main entrance faces Round Rock Ave.; secondary entrance and parking lot on SE side.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other 5 parking spaces on site

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☒ Other mansard

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☒ Other large display

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☒ Other single door 2nd entry

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☒ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other eaves all around

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☒ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1965 ☐ Actual ☒ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Former site of cotton yard warehouse; later was a residential lot.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☒ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 23, LOT 5-7

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-148

1. Identification

County Williamson City Round Rock

Current name Golden Chick Restaurant Historic name _____

Address 400 Round Rock Avenue

Owner/address W G G INTERESTS INC., 404 W. LIBERTY AVE., ROUND ROCK,TX 78664

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Fast-food restaurant with drive-thru along west/front facade. Red, yellow, and white parapet with chick logo.

Yellow stnd. seam roof overhangs S and E sides; sign centered E side. Fieldstone veneer; window walls with black/white checked painted metal base.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Large parking lot w/16 spaces. Picnic tables north side of building.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☒ Other Fast food

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☒ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☒ Metal standing seam
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

3 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☒ Fieldstone veneer
☐ Awning(s)
☒ Other window wall

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☒ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☒ Rectangular
☐ Other _____

Foundation:

☒ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1979 ■ Actual ☐ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 31, LOT 1-4

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-149

1. Identification

County Williamson City Round Rock

Current name Law Offices of Cummings and Walsh Historic name _____

Address 405 Round Rock Avenue

Owner/address PATRICIA J. CUMMINGS, 405 ROUND ROCK AVE., ROUND ROCK,TX 78664-5143

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Side gable w/ stone veneer, standing-seam metal roof. Multiple French doors. Gabled awning over main entry.

Rear faces West Liberty, with a double sash window, single entry door, small window and three flanking two French doors. Parking available in rear.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☒ Other 5 on-site parking spaces

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☒ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☒ Metal standing seam - dark gr
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- ____ Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☐ Siding, type _____
- ☒ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☒ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☒ With sidelights
- ☒ Other multiple French doors

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☒ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☒ Other awning with metal poles
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

D-149

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1950 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 31, LOT 5 ALL, 6 & 13 PTS OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ■ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-150

1. Identification

County Williamson City Round Rock

Current name Round Rock Travel and Tours Historic name _____

Address 407 Round Rock Avenue

Owner/address WILLIAM H & MARY ELIZABETH PECKHAM, 8708 BALCONES CLUB DR, AUSTIN,TX 78750-3004

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Side gable bldg with notched parapet/pediment over entry. Brown wood siding on front facade, tan T-111 type siding on sides and back. Rear lot from building to West Liberty Street is all gravel.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other 4 on-site parking spaces in front, 6 in back.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☒ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
- ☐ gable
- ☐ hipped
- ☐ shed

☒ Other Parapet/pediment over

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☒ Metal standing seam - galvan
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type Wood on front fac
☐ Fieldstone veneer
☐ Awning(s)
☒ Other T-111 siding on sides, re

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☒ Double hung
☐ Casement
☒ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☒ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☒ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other Giant porch cover

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1988 ■ Actual ☐ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Lot behind building has same address but is considered separate parcel; see D-151

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ■ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 31, LOT 12 & 13 PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ■ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-151

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address No Number Round Rock/Liberty Avenue, located behind 407 Round Rock Avenue (Round Rock Travel)

Owner/address WILLIAM H. PECKHAM III & MARY E. PECKHAM, TR. PECKHAM TRUST, 8708 BALCONES CLUB DR., AUSTIN,TX 78750-3004

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Vacant lot; mostly gravel.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 31, LOT 6 PT & 7

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

_____

_____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-152

1. Identification

County Williamson City Round Rock

Current name Tio Dan Puffy Tacos Mexican Restaurant Historic name Dairy Kreme

Address 409 Round Rock Avenue

Owner/address DONALD HESTER, 13 LAKE DR., ROUND ROCK,TX 78664-9415

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Original Dairy Kreme building consists of just the section under the large front gable. Roof modified with large low-pitch gable, eaves across front facade. Single doors on outside bays. Alum fixed windows in upper half of wall with brick veneer below.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other Parking lot with 19 spaces surrounds restaurant

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☒ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☒ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- 5 Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type wood, plywood
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☒ Other brick veneer, CMU

Chimneys:
- 0 Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☒ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☒ Other 2 of these

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☒ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☒ Other over eaves
☐ Box columns	

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1962 ■ Actual ☐ Estimated Source: WCAD

■ Additions/modifications, specify dates: Expanded; date unknown

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 31, LOT 10 & 11

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-153

1. Identification

County Williamson City Round Rock

Current name Wells Fargo Bank Historic name _____

Address 505 Round Rock Avenue (corner of Round Rock Ave. and San Saba Street)

Owner/address NORWEST BANK TEXAS, C/O WELLS FARGO BANK-TAX DEPT., P.O. BOX 63931, SAN FRANCISCO,CA 94163

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Bank building with fieldstone veneer, large pediment cover over main entrance porch W side. Standing seam metal roof. Four-lane drive-thru on E side. Two driveways from San Saba Street.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other Large parking lot on W side facing IH-35.

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ■ Other Landscaped with mature trees, hedges, grassy medians

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	■ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
■ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
■ Other gable over drive-thru

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
■ Metal standing seam
☐ Other _____

Construction:

■ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
■ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
■ Double-door primary entrance
☐ With transom
■ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
■ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
■ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
■ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 8640

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1981 ■ Actual ☐ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 30 AND VACATED STREETS & ALLEY

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-154

1. Identification

County Williamson City Round Rock

Current name _____ Historic name William J. Walsh House

Address 106 North San Saba Street

Owner/address DOROTHY MUNSON, 6100 GENA CT, AUSTIN,TX 78757-4434

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Two-story L-shaped Craftsman house with hipped roof and porch roof. Porch has piers with tapered box columns. Outbuildings include sheds and small barn/garage.

Outbuildings (Specify number and type):

Garage _____ Barn 1 Shed 2 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

4 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

1 Specify number(s)
☒ Interior
☐ Exterior
☒ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☒ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☒ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☒ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☒ Other side porch on south

Stories: 2 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2556

3. Integrity

☒ Location ☒ Design ☒ Materials ☐ Workmanship ☒ Setting ☒ Feeling ☒ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☒ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1903 ☒ Actual ☐ Estimated Source: "Historical Round Rock," page 283

☒ Additions/modifications, specify dates: Heavily altered to Craftsman style ca. 1920; removed second-floor porch and decorative details

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: One of two properties that abuts/includes large open lot common in early development.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ☒ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☒ Yes ☐ No ☐ Not known **Type:** ☐ HABS ☒ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☒ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
☒ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 27, LOT 4-6

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☒ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☒ High ☐ Medium ☐ Low

Explain Local Landmark

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-155

1. Identification

County Williamson City Round Rock

Current name Vacant lot Historic name _____

Address No Number North San Saba (south of 106 N. San Saba)

Owner/address DOROTHY MUNSON, 6100 GENA CT., AUSTIN,TX 78757-4434

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-acre vacant lot adjacent to 106 North San Saba with large oak tree near center.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☐ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☐ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☐ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

____ Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☐ Siding, type _____
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

____Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☐ Wood sash
☐ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☐ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☐ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☐ Pier and beam
☐ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☐ Gable roof
☐ Inset
☐ Wood posts
☐ Brick piers
☐ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: _____ **Basement:** ☐ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet _____

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare ☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: _____ ☐ Actual ☐ Estimated Source: _____

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect ■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 27, LOT 1-3, & AW0298 HARRIS, S SUR., TRACT 2

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-156

1. Identification

County Williamson City Round Rock

Current name Warehouse Historic name _____

Address No Street Number, North Sheppard Street

Owner/address Jane Hilliard, 927 Oak Grove Loop, China Spring,TX 76633

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Large blue barn/garage/warehouse, appears to be vacant or inactive.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ■ Other about 4 on-site parking spaces

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	■ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

- ■ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☐ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ■ Other Bracketed eaves

Roof Materials:

- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ■ Metal Corrugated
- ☐ Other _____

Construction:

- ■ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:

N/A Number of bays

- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ■ Siding, type Aluminum
- ☐ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:

0 Specify number(s)

- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:

- ☐ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ■ Other No windows

Doors:

- ■ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ■ Other Large sliding barn doors

Plan:

- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ■ Rectangular
- ☐ Other _____

Foundation:

- ■ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:

☐ Shed roof	☐ Classical columns
☐ Hipped roof	☐ Tapered box supports
☐ Gable roof	☐ Fabricated metal
☐ Inset	☐ Spindlework
☐ Wood posts	☐ Jig-sawn trim
☐ Brick piers	☐ Other _____
☐ Box columns	

Stories: 1 possible loft **Basement:** ■ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 2700

3. Integrity

■ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ■ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1960 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Was owned by Lamme family.

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ■ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 20, LOT 8-9 N PTS OF

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ■ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-157

1. Identification

County Williamson City Round Rock

Current name Kuno's (bar) and Historic name

Address 109 North Sheppard Street

Owner/address VINCENT SANCHEZ, 204 E. ANDERSON AVE., ROUND ROCK,TX 78664-5204

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☐ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description One-story bar wth faux mansard-style roof on upper part of front facade. Rest of facade is mix of rubble and ashlar stone veneer, with plywood siding on north end of building. Single entry door and small windows. Stepped sign projects above roofline.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☐ Sidewalks ☐ Terracing ☐ Drives ☐ Well/cistern ☐ Gardens ☐ Other _____

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☐ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☒ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:
- ☐ Gable
- ☐ Hipped
- ☐ Gambrel
- ☐ Shed
- ☒ Flat w/parapet
- ☐ Dormers:
  - ☐ gable
  - ☐ hipped
  - ☐ shed
- ☐ Other _____

Roof Materials:
- ☐ Wood shingles
- ☐ Tile
- ☐ Composition shingles
- ☐ Metal _____
- ☐ Other _____

Construction:
- ☒ Frame
- ☐ Adobe
- ☐ Solid brick
- ☐ Solid stone
- ☐ Other _____

Wall Facade:
- ?___ Number of bays
- ☐ Stucco
- ☐ Stone
- ☐ Brick
- ☐ Wood shingle
- ☐ Log
- ☐ Terra Cotta
- ☐ Metal
- ☒ Siding, type plywood
- ☒ Fieldstone veneer
- ☐ Awning(s)
- ☐ Other _____

Chimneys:
- 0___Specify number(s)
- ☐ Interior
- ☐ Exterior
- ☐ Brick
- ☐ Stone
- ☐ With corbelled caps
- ☐ Stuccoed
- ☐ Other _____

Windows:
- ☒ Fixed
- ☐ Wood sash
- ☐ Double hung
- ☐ Casement
- ☐ Aluminum sash
- ☐ Decorative screenwork
- ☐ Other _____

Doors:
- ☒ Single-door primary entrance
- ☐ Double-door primary entrance
- ☐ With transom
- ☐ With sidelights
- ☐ Other _____

Plan:
- ☐ L-plan ☐ 2-room
- ☐ T-plan ☐ Open
- ☐ Modified L-plan
- ☐ Center passage
- ☐ Bungalow
- ☐ Shotgun
- ☐ Irregular
- ☐ Four Square
- ☒ Rectangular
- ☐ Other _____

Foundation:
- ☒ Slab ☐ Pier and beam
- ☐ Perimeter wall
- ☐ Other _____

Porches:
- ☐ Shed roof
- ☐ Hipped roof
- ☐ Gable roof
- ☐ Inset
- ☐ Wood posts
- ☐ Brick piers
- ☐ Box columns
- ☐ Classical columns
- ☐ Tapered box supports
- ☐ Fabricated metal
- ☐ Spindlework
- ☐ Jig-sawn trim
- ☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 4583

3. Integrity

☐ Location ☐ Design ☐ Materials ☐ Workmanship ☐ Setting ☐ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1940 ☐ Actual ■ Estimated Source: WCAD

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ☐ Yes ■ No ☐ Not known **Type:** ☐ HABS ☐ Survey ☐ Other_____

Details: _____

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 20, LOT 10

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ☐ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-158

1. Identification

County Williamson City Round Rock

Current name Vacant - for lease (was Tramex Travel) Historic name Francis and Edith Sandburg House

Address 107 South Sheppard Street

Owner/address JUAN & MARGO PORTILLO, 4505 SPICEWOOD SPRINGS RD #200, AUSTIN,TX 78753

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Excellent example of Craftsman bungalow. Hipped roof with front gable, exposed bracketed eaves, attic vent in porch gable. Inset porch. Windows appear to be original.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed 1 Other _____

☐ Archeological evidence of outbuildings, specify _____

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☐ Other Handicapped access on north side - wooden ramp and handrail

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☒ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☒ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☒ Gable roof
☒ Inset
☐ Wood posts
☒ Brick piers
☒ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1148

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☒ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1927 ■ Actual ☐ Estimated Source: Historic building placard

■ Additions/modifications, specify dates: Rear screened porch enclosed in 1940s

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Incorporated lumber and windows from old Stamline house at 303 East Main

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ■ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): PORTILLO SUB, BLOCK 11, Lot 1

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

■ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: 1930-1970

Level of significance: ☐ National ☐ State ■ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ■ High ☐ Medium ☐ Low

Explain _____

TEXAS HISTORICAL COMMISSION

HISTORIC RESOURCES SURVEY FORM

D-159

1. Identification

County Williamson City Round Rock

Current name Gordon Mackey, CPA Historic name

Address 109 South Sheppard Street

Owner/address JUAN & MARGO PORTILLO, 4505 SPICEWOOD SPRINGS RD #200, AUSTIN,TX 78753

Photo data: Roll _____ Frame _____ to Roll _____ Frame _____

Current Designations: ☐ NR ☐ NR District (Is property contributing? ☐ Yes ☐ No) ☐ RTHL ☐ HTC ☐ SAL ☒ Local ☐ Other

Recorded by: Steph McDougal, McDoux Preservation LLC Date recorded: March 1-3, 2010

General architectural description Excellent Craftsman bungalow. Hipped roof with front gable over inset porch. Brick piers and box columns. Wood siding and windows appear to be original. Most of yard has been paved for parking.

Outbuildings (Specify number and type):

Garage _____ Barn _____ Shed _____ Other Rear outbuilding seems to be additional office space(s) with 2 doors, multiple windows.

☐ Archeological evidence of outbuildings, specify

Landscape/site features:

☒ Sidewalks ☐ Terracing ☒ Drives ☐ Well/cistern ☐ Gardens ☒ Other Handicapped access on north side, designed to match porch.

2. Architectural Description

Stylistic Influence(s):

☐ Log Traditional	☐ Shingle	☐ Gothic Revival	☐ Pueblo Revival	☐ International
☐ Greek Revival	☐ Romanesque Revival	☐ Tudor Revival	☐ Spanish Colonial	☐ Post-war Modern
☐ Italianate	☐ Folk Victorian	☐ Neo-Classical	☐ Prairie	☐ Ranch Style
☐ Second Empire	☐ Colonial Revival	☐ Beaux Arts	☒ Craftsman	☐ Commercial Style
☐ Eastlake	☐ Renaissance Revival	☐ Mission	☐ Art Deco	☐ No Style
☐ Queen Anne	☐ Exotic Revival	☐ Monterey	☐ Moderne	☐ Other _____

Structural Details:

Roof Type:

☐ Gable
☒ Hipped
☐ Gambrel
☐ Shed
☐ Flat w/parapet
☐ Dormers:
  ☐ gable
  ☐ hipped
  ☐ shed
☐ Other _____

Roof Materials:

☐ Wood shingles
☐ Tile
☒ Composition shingles
☐ Metal _____
☐ Other _____

Construction:

☒ Frame
☐ Adobe
☐ Solid brick
☐ Solid stone
☐ Other _____

Wall Facade:

2 Number of bays
☐ Stucco
☐ Stone
☐ Brick
☐ Wood shingle
☐ Log
☐ Terra Cotta
☐ Metal
☒ Siding, type wood
☐ Fieldstone veneer
☐ Awning(s)
☐ Other _____

Chimneys:

0 Specify number(s)
☐ Interior
☐ Exterior
☐ Brick
☐ Stone
☐ With corbelled caps
☐ Stuccoed
☐ Other _____

Windows:

☐ Fixed
☒ Wood sash
☒ Double hung
☐ Casement
☐ Aluminum sash
☐ Decorative screenwork
☐ Other _____

Doors:

☒ Single-door primary entrance
☐ Double-door primary entrance
☐ With transom
☐ With sidelights
☐ Other _____

Plan:

☐ L-plan ☐ 2-room
☐ T-plan ☐ Open
☐ Modified L-plan
☐ Center passage
☒ Bungalow
☐ Shotgun
☐ Irregular
☐ Four Square
☐ Rectangular
☐ Other _____

Foundation:

☐ Slab ☒ Pier and beam
☒ Perimeter wall
☐ Other _____

Porches:

☐ Shed roof
☐ Hipped roof
☒ Gable roof
☒ Inset
☐ Wood posts
☒ Brick piers
☒ Box columns
☐ Classical columns
☐ Tapered box supports
☐ Fabricated metal
☐ Spindlework
☐ Jig-sawn trim
☐ Other _____

Stories: 1 **Basement:** ☒ None ☐ Partial ☐ Full **Dimensions:** L _____ x W _____ = Square feet 1148

3. Integrity

☒ Location ☒ Design ☒ Materials ☒ Workmanship ☐ Setting ☒ Feeling ☐ Association

4. Function

Historic Use: ☐ Agriculture ☐ Commerce/trade ☐ Defense ■ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Other _____

Current Use: ☐ Agriculture ■ Commerce/trade ☐ Defense ☐ Domestic ☐ Educational ☐ Government ☐ Healthcare
☐ Industry/processing ☐ Recreation/culture ☐ Religious ☐ Social ☐ Vacant ☐ Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: 1927 ■ Actual ☐ Estimated Source: Building placard

☐ Additions/modifications, specify dates: _____

☐ Relocated, specify former location and reason: _____

Other associated contexts and information of interest: Identical to 107 S. Sheppard but built with all new materials

6. Archeology Ground

☐ Original state ☐ Disturbed Explain _____

Is a State Archeological Survey Form available for this site? ☐ Yes ☐ No ■ Not known

Details: _____

7. Other Information

Is prior documentation available for this resource? ■ Yes ☐ No ☐ Not known **Type:** ☐ HABS ■ Survey ☐ Other_____

Details: Historic Resources Survey 1992 on file at City Planning Department and THC History Programs Division

Accessible to the public: ☐ Yes ☐ No ☐ Not known **Possible threat(s):** ☐ None ☐ Damage (i.e. natural disaster) ☐ Neglect
■ Development ☐ Major alteration ☐ Relocation ☐ Other _____* **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 3097-312 Year: 1987 Map scale: 1:24 000

UTM zone: 14 Easting: _____ Northing: _____

Legal description (Lot/Block): CITY OF ROUND ROCK, BLOCK 11, LOT 7 SW PT & 8-10 S PT

Addition: _____ Year of addition: _____

9. Significance

Applicable National Register (NR) criteria:

☐ A. Associated with events that have made a significant contribution to the broad pattern of our history;

☐ B. Associated with the lives of persons significant in our past;

☐ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;

☐ D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: _____

Period(s) of significance: _____

Level of significance: ☐ National ☐ State ☐ Local

Possible NR district: ☐ Yes ☐ No **Is property contributing?** ■ Yes ☐ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☐ Low

Explain _____